<b>★</b> Re	Roll Call Number						Agenda Item Number	
Da	nte <u>July</u>	29, 201	13				•	
		SAK C	CONST 20	RUCT	ION, L	HANGE ORDER NO. 1 WITH LC FOR ADDITIONAL WORK O SANITARY SEWER LINING L NOT TO EXCEED \$91,290	N THE	
Or Pro Se	der No. 1 esident, 86 wer Linin	between 4 Hoff g, in an	en the Road, Contains	City o O'Fallo nt not	f Des Mon, MO, to exce	f the City of Des Moines, Iowa, that the Moines and SAK Construction, LLC, 63366, for additional work on the 201 appropriate \$91,290, be and is hereby appropriate said change order.	Boyd Hirtz, Vice 11 Critical Sanitary	
				(Cou	ncil Lett	ter Number <u>18394</u> attached)		
				·		vity ID 07-2011-009		
	Moved by <sub>.</sub> FORM AP		ED: <u>1</u>	James	,	to adopt.		
	Funding So SS049	ource: 2	De	eputy C	City Atto	_	d Lateral Sewers,	
	IL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE	<b>=</b>	
COWN	(IE			ļ		I. DIANE RAUH, City Clerk (	of said City hereby	

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
COLEMAN				
GRIESS				
HENSLEY				
MAHAFFEY				
MEYER				
MOORE				
TOTAL				
MOTION CARRIED			A	PPROVED

Mayor

I, DIANE RAUH, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

	ity Clerk
--	-----------

## ENGINEERING DEPARTMENT CITY OF DES MOINES, IOWA



## **CHANGE ORDER AGREEMENT NO. 1**

Date:

July 11, 2013

**INITIATED BY:** 

Contractor

Contractor:

SAK Construction, LLC

Project:

2011 Critical Sanitary Sewer Lining

**Activity ID:** 

07-2011-009

## DESCRIPTION OF CHANGE ORDER AND PURPOSE

The 10" sanitary sewer located under the pond in Glendale Cemetery was found to be severely out of alignment. Because of this severe misalignment, the sanitary sewer could not be cleaned, televised, or lined. Dewater the pond, remove accumulated sediment, and remove and replace the sanitary sewer to correct the alignment issues.

SETTLEMENT FOR COST OF CHANGED WORK						
B. ITEM	IS FOR WHICH CONTRACT UNIT PRICES ARE NOT ESTABLISHED:					
ITEM_	DESCRIPTION	UNITS	UNIT PRICE	AMOUNT		
1.01 Repair 10	Repair 10" sanitary sewer under pond	1.0000 LS	\$91,290.00	\$91,290.00		
		NET CHANGE PART B		\$91,290.00		
			= TOTAL	\$91,290,00		

Original Contract Amount \$3,550,605.00

**Previous Change Orders** 

\$0.00

Amount of Change By This Change Order

\$91,290.00

**New Contract Amount Including This Change Order** 

\$3,641,895.00

Percentage of Change Orders to Original Contract

2.57%

7- [9-12]
et Hansen P.B.
Date

Jeb B. Brewer, P.E.

Des Moines City Engineer

Date

SAK Construction, LLC

0-13

General Manager

Richard A. Clark

Date

City Manager

Roll Call No.

Date

Distribution:

Original - Project File

Copy - Prime Contractor

Copy - Contract Compliance Copy - Finance Department

Copy - Inspection

Copy -Jeff Hansen, P.E.

Civil Engineer 2

FUNDING INFORMATION						
CIP Page	Sanitary-13	Reviewer	DJL			
Object Code	543040	Adequate				
Organization	PWK990000	Transfer \$				
Project	SAE049	Object Code				
Activity ID	072011009	Organization				
		Project				

Remove and replace the misaligned 10" sanitary sewer under Glendale Cemetery pond.