

Date <u>April 20, 2020</u>

ABATEMENT OF PUBLIC NUISANCE AT 1325 22nd STREET

WHEREAS, the property located at 1325 22nd Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Pals Services, LLC, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as South 16 feet of Lot 358 and North 22 feet of Lot 359 in UNIVERSITY LAND CO'S 2nd ADDITION, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1325 22nd Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM APPROVED:

<u>/s/ Megan Norberg</u> Megan Norberg, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, P. Kay Cmelik, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GRAY					other proceedings the above was adopted.
MANDELBAUM					other proceedings and a set and and i
VOSS					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first
TOTAL					above written.
MOTION CARRIED			API	PROVED	
				Manan	City Clerk
				Mayor	

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904



1

			L	ocation			
Address	1325	22ND ST					
City		DES MOINES	Zip		50311	Jurisdiction	Des Moines
strict/Parcel	080/	06766-000-000	Geoparcel	7924	-33-452-015	Status	Active
School			Nbhd/Pocket		DM75/Z	Tax Authority Group	DEM-C-DEM- 77131
Submarket	Nor	thwest Des Moines			drew Rand 515- 286-3368		
			Map and Cu	rrent P	hotos - 1 Rec	ord	
Clic	k on	parcel to get a	new listing				
1334 1332		1339	133	38	Ph	noto Processed on 2	2012-04-16 a
1330 1326		1333	1:	332	2		an felt v
1316 1324 1320 1318	2	1329	132	8	(1 		
	22ND ST	1325		20			
1314	ST	1311				AND AND A COMPANY OF A DECIMAL	
1312		1309					. Ma
1310		1305			TO		
	Bigger	Map Polk Cou	<u>inty GIS</u>				
	<u>Goo</u>	<u>gle Map Picto</u>	ometry Hi	storica	l Photos		
					l Record		
-		DT		me		Recorded	Book/Page
Ownershi Title Holder		Num 1	PALS SERVIC		.C	2019-12-31	17650/811
Thie Holder		-	legal Descripti	And and the second s		lress	
					0		
S 16 FT LO COS 2ND A	T 358 ADDI	& N 22 FT LO FION	T 359 UNIVEI	RSITY	LAND	PALS SERV 9320 NE 94 BONDURA	
			Cu	rrent V	alues		
		Class		Kind	Lan		
Type				77 11	¢0.00	0 \$66,000	\$75,000
Type 2019 Value		Residentia		Full	\$9,00 <u>Cost Report</u>	υ φυσ,υσο	¢,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

	Zoning - 1 Record						
	Description	SF	Assessor Zoning				
Zoning	*		Multi-Family Residential				
R-3	Multiple Family Residential District	TTI D					
City of Des	Moines Community Development Planning and	Urban De.	sign 515 265-4162 (2012-05-20)				

4/3/2020

Polk County Assessor 080/06766-000-000

		Land			20.0
Square Feet	5,966	Acres	0.137	Frontage	38.0
Depth		Topography	Normal	Shape	Rectangle
Vacancy		Unbuildable	No		
		Residences - 1	Record		
		Residence			Early
Occupancy	Conversion	Residence Type	2 Stories Plus	Building Style	20
Year Built	1911	Number Families	2	Grade	4+00
Condition	Normal	Total Square Foot Living Area	1579	Main Living Area	672
Upper Living Area	672	Attic Finished Area	235	Basement Area	672
Open Porch Area	168	Foundation	Brick	Exterior Wall Type	Woo Sidin
Roof Type	Gable	Roof Material	Asphalt Shingle	Heating	Ga Force
Air	0	Number Bathrooms	3	Number Extra Fixtures	
Conditioning Bedrooms	5	Rooms			
	28	<u>1/2 atti 25 85mt</u> 672	<u>c</u>	28	
	28	<u>1/2 atti 25</u> Bsmt 672 24 24 Porch 168		28	

Sales	-	6	Records
Dailos		v	TTO COL CHO

Seller	Buyer	Sale Date	Sale Price	Instrument	Book/Page
BELDING, JASON R	PALS SERVICES, LLC	<u>2019-12-31</u>	\$7,500	Deed	<u>17650/811</u>
DEUTSCHE BANK NATIONAL TRUST CO	BELDING, JASON	<u>2005-04-13</u>	\$26,000	Deed	<u>11069/774</u>
PRIMO ACQUISITIONS, I LLC	HALE, JOANN	<u>2003-01-23</u>	\$87,000	Deed	<u>9609/508</u>
PRIMO ACQUISITIONS, I LLC	GONZALEZ, SALVADOR	<u>1999-06-02</u>	\$50,000	Contract	<u>8256/745</u>
RIGSBY, JAMES T	BRIGHT, WILLIAM	<u>1998-06-17</u>	\$26,000	Contract	<u>7987/51</u>
UNIVERSAL SAVINGS BANK	SECRETARY OF HUD	<u>1992-02-21</u>	\$12,720	Deed	<u>6525/800</u>

Recent Ownership Transfers

Granto	r	Grantee	Instrument Date	Reco Date	rding	Instrument Type	Book/Pg
BELDIN JASON BELDIN KATHI KOHLS ERIC J KOHLS BROOI	R NG, LEEN SDORF, SDORF,	PALS SERVICES LLC	2019-12-31	2019 31	-12-	Quit Claim Deed	<u>17650/811</u>
Ditter	Permits - 2 Records						
Year	Туре	Permit Status Application Description				on	

Year	Type	rer mit Status	rpp	
	Permit	Complete	2005-08-17	alterations/remodel (40 sf)
2000		company		Cl 1 main
1995	Permit	No Add	1994-03-04	flood repair

Historical Values

* 7	Three a	Class	Kind	Land	Bldg	Total	
Yr	Туре		Full	\$9,000	\$66,000	\$75,000	
2019	Assessment Roll	Residential			\$62,800	\$71,300	
2017	Assessment Roll	Residential	Full	\$8,500			
	Assessment Roll	Residential	Full	\$7,900	\$58,500	\$66,400	
2015		Residential	Full	\$7,200	\$53,100	\$60,300	
2013	Assessment Roll				\$53,100	\$60,300	
2011	Assessment Roll	Residential	Full	\$7,200			
	Assessment Roll	Residential	Full	\$7,500	\$53,100	\$60,600	
2009		Residential	Full	\$7,200	\$50,900	\$58,100	
2007	Assessment Roll			\$4,300	\$37,800	\$42,100	
2006	Assessment Roll	Residential	Full				
2005	Assessment Roll	Residential	Full	\$4,300	\$39,300	\$43,600	
		Residential	Full	\$3,490	\$31,450	\$34,940	
2003	Assessment Roll	Residential	1 411	4-,150			

Polk County Assessor 080/06766-000-000

/3/2020			Class	Kind	Land	Bldg	Total
-	Yr	Type	Residential	Full	\$3,750	\$25,220	\$28,970
	2001	Assessment Roll	Residential	Full	\$3,880	\$19,870	\$23,750
	1999	Assessment Roll		Full	\$3,580	\$18,350	\$21,930
	1997	Assessment Roll	Residential	Full	\$3,370	\$16,480	\$19,850
	1995	Assessment Roll	Residential		\$2,920	\$16,480	\$19,400
	1989	Assessment Roll	Residential	Full	\$2,920	φ10,100	

This template was last modified on Sat Mar 4 12:31:48 2017 .



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: Februa	ry 19, 2020	DATE OF INSPECTION:	August 23, 2019
CASE NUMBER:	COD2019-05111		
PROPERTIADDICESS	1325 22ND ST		
LEGAL DESCRIPTION:	S 16 FT LOT 358 & N 22 FT	LOT 359 UNIVERSITY LAND	COS 2ND ADDITION

PALS SERVICES LLC Title Holder - KYLE PALS, REG AGENT 9320 NE 94TH ST BONDURANT IA 50035

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

VCDMAPPS1\D_VOLUME\APPDATA\Tidemark\prd_41\Forms & Reports\dsmCODPubNo.rp

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Brad Rissman (515) 283-4754

Nid Inspector

DATE MAILED: 2/19/2020

MAILED BY: BJR

25K

Areas that need attention: 1325 22ND ST

	d attention: 1325 22ND ST	Defectu	In disrepair
Component:	Stairs/Stoop	Defect:	In disrepan
<u>Requirement:</u>	Complaince with Int Residential Code		Main Structure Throughout
<u>Comments:</u>	Have licensed contractor repair or replace for replacement of all structural componen	all damaged ts.	d components, Permit required
Component:	Water Heater	Defect:	In disrepair
Requirement:	Plumbing Permit	Location:	Basement
<u>Comments:</u>	Have licensed contractor repair or replace residential building code.		
2	Flactrical System	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Electrical System Electrical Permit		Main Structure Throughout
-			
<u>Comments:</u>	Have licensed contractor repair or replace components up to code. In compliance wi	electrical s th internation	onal residential building code.
	Electrical Lighting Fixtures	Defect:	In poor repair
<u>Component:</u> Requirement:	Electrical Permit		
Requirements			Main Structure Throughout
<u>Comments:</u>	Have licensed contractor bring system up residential building code.	to code. In	compliance with international
	Electrical Receptacles	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Electrical Permit		: Main Structure Throughout
<u>Comments:</u>	Have licensed contractor bring system up residential building code.		
	Exterior Doors/Jams	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Complaince with Int Residential Code	Location	. Main Structure Throughout
<u>Comments:</u>	Repair or replace all damaged or missing required if changing opening size.		
		Defect:	In disrepair
<u>Component:</u> <u>Requirement:</u>	Exterior Stairs Building Permit		n Main Structure Throughout
<u>Comments:</u>	Have licensed contractor repair or replace hand rail, and stairs. Permit required for	re damage (decking, railing, joist, beams,
Commonweit	Exterior Walls	Defect:	In disrepair
<u>Component:</u> <u>Requirement:</u>	in the transformed Code		n: Main Structure Throughout
<u>Comments:</u>	Have licensed contractor repair or repla framing, sheeting, and coverings. Permi components.	ce all dama	ged wall components, including

WCOMARDELLD VOLUME\APPDATA\Tidemark\prd 41\Forms & Reports\dsmCODPubNo.rp

Component: Requirement: Comments: Component: Requirement: Comments:	Floor Joists/Beams Complaince with Int Residential CodeDefect:In disrepairHave licensed contractor repair or replace all damaged joist and beams. Permit required for replacement of all structural components.Joist and beams. PermitFlooring Complaince with Int Residential CodeDefect:In disrepairFlooring Complaince with Int Residential CodeLocation:Main Structure ThroughoutRepair or replace all damaged or missing flooring components.Main Structure Throughout
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Foundation Defect: In disrepair Building Permit Location: Main Structure Throughout Need Engineers Report. Repair or replace per engineers report by licensed contractor. Contractor
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	FurnaceDefect:In disrepairMechanical PermitLocation:BasementHave licensed contractor repair or replace system. Bring any and all components up to code.Enderson of the system of the
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Guardrails Defect: In disrepair Complaince with Int Residential Code Location: Main Structure Throughout Repair or replace all damaged or missing components as needed. Structure Throughout
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Hand RailsDefect:In disrepairComplaince with Int Residential CodeLocation:Main Structure ThroughoutRepair or replace all damaged or missing components as needed.
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Interior Walls /Ceiling Defect: In disrepair Complaince with Int Residential Code Location: Main Structure Throughout Have licensed contractor repair or replace all damaged interior wall and ceiling components. Permit may be required. In disrepair
<u>Component:</u> <u>Requirement:</u> <u>Comments:</u>	Mechanical System Defect: In disrepair Mechanical Permit Location: Main Structure Throughout Have licensed contractor repair or replace mechanical system. Bring any and all components up to code. In compliance with international residential building code.
<u>Component:</u> <u>Requirement</u> <u>Comments:</u>	Plumbing System Defect: In disrepair Plumbing Permit Location: Main Structure Throughout Have licensed contractor repair or replace plumbing system. Bring any and all components up to code. In compliance with international residential building code.

Commencent	Roof	Defect:	In disrepair
<u>Component:</u> <u>Requirement:</u>	Complaince with Int Residential Code	Location:	Roof
<u>Comments:</u>	Repair or replace all damaged or missing roofing components as needed. Permit required for repairs other than shingles.		
Component:	Shingles Flashing	Defect:	In disrepair
Requirement:	Complaince with Int Residential Code	Location:	Roof
Comments:	Replace all damaged and missing.		
Component:	Smoke Detectors	Defect:	Missing
Requirement:	Building Permit	Location:	Main Structure Throughout
<u>Comments:</u>	In compliance with international residenti	al building c	ode.
Component:	Soffit/Facia/Trim	Defect:	In disrepair
<u>Requirement:</u>	Complaince with Int Residential Code	Location:	Main Structure Throughout
Comments:	Repair or replace all damaged or missing components, cover to match.		
Component:	Windows/Window Frames	Defect:	In disrepair
Requirement:	Complaince with Int Residential Code	Location:	Main Structure Throughout
<u>Comments:</u>	Repair or replace all damaged or missing windows and frames as needed. Permit required if changing opening size.		
Component:	Wiring	Defect:	In poor repair
<u>Component:</u> <u>Requirement:</u>	Wiring Electrical Permit		In poor repair Main Structure Throughout
		Location	Main Structure Throughout



