7			F	?	)		(	7 (	S	1		P	I	Į	J	ľ	7	1	)	E	)	r				

Agenda Iter	n Nur	nber
S	LIA	B

	11.0			
Date	Inly	13	2020	

## ABATEMENT OF PUBLIC NUISANCE AT 2513 WOODLAND AVENUE

WHEREAS, the property located at 2513 Woodland Avenue, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Harlan Howard Thomas, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 24 (except the West 95 feet thereof) in WOODLAND PLACE, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2513 Woodland Avenue, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

	Moved by	to adopt.
FORM APPROVED:		
/s/ Megan Norberg Megan Norberg, Assistant City Attorney		

Mayor

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
GATTO				
GRAY				
MANDELBAUM				
VOSS				
WESTERGAARD				
TOTAL				
MOTION CARRIED			AP	PROVED

## **CERTIFICATE**

I, P. Kay Cmelik, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

City Clerk
9

2513 Woodland Ave top 06/29/2020 12:54





# PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA



DATE OF NOTICE: February 18, 2020

DATE OF INSPECTION:

February 11, 2020

CASE NUMBER:

COD2020-00929

**PROPERTY ADDRESS:** 

2513 WOODLAND AVE

**LEGAL DESCRIPTION:** 

E 37 F LOT 24 WOODLAND PLACE

HARLAN HOWARD THOMAS Title Holder 1425 IDAHO ST DES MOINES IA 50316-2423

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

49B

Appropriate building permits may be required for those violations noted in the "Special Requirements" section or the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Neighborhood Inspection Division

(515) 283-4046

Nid Inspector

DATE MAILED: 2/18/2020

MAILED BY: TSY

# Areas that need attention: 2513 WOODLAND AVE


	ed attention: 2513 WOODLAND AVE		
Component: Requirement:	Soffit/Facia/Trim Complaince with Int Residential Code	Defect:	Absence of paint
<u>-sagamementa</u>	complaince with the Residential Code	Location:	Main Structure Throughout
Comments:	Scrape and paint to match any damaged		_
	scrape and paint to mater any damaged	or rotten th	m and rascia.
Component:	Exterior Doors/Jams	Defect:	Cracked/Broken
Requirement:	Complaince with Int Residential Code		
Comments:			Main Structure Throughout
	Repair and replace any doors that are mis	ssing or inop	perable
Component:	Exterior Walls	Defect:	Excessive rot
Requirement:	Complaince with Int Residential Code	BCICCL	LACESSIVE TOL
Comments:		Location:	Main Structure
<u>comments.</u>	Repair rotten wood underneath front door	entrance a	nd paint to match
Component:	Exterior Walls	Deferi	
Requirement:	Complaince with Int Residential Code	Defect:	Holes or major defect
	The Residential Code	Location:	Main Structure Throughout
Comments:	Replace siding with like materials . Paint to		3
Component:	Soffit/Facia/Trim	Defect:	Missing Sections
Component: Requirement:	Soffit/Facia/Trim Complaince with Int Residential Code		
	Complaince with Int Residential Code	Location:	Main Structure Throughout
Requirement:		Location:	Main Structure Throughout
Requirement:	Complaince with Int Residential Code	Location:	Main Structure Throughout
Requirement:  Comments:  Component:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames	Location:	Main Structure Throughout
Requirement: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a	Location: are missing.  Defect:	Main Structure Throughout Paint to match.  Severly peeling paint
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code	Location: re missing.  Defect: Location:	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout
Requirement:  Comments:  Component:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames	Location: re missing.  Defect: Location:	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code	Location: re missing.  Defect: Location:	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.	Location: re missing.  Defect: Location: Paint to ma	Main Structure Throughout Paint to match.  Severly peeling paint  Main Structure Throughout atch.
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code	Location: re missing.  Defect: Location:	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout
Requirement: Comments: Component: Requirements: Comments: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof	Location: The missing.  Defect: Location: Paint to ma	Main Structure Throughout Paint to match.  Severly peeling paint  Main Structure Throughout atch.
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-	Location: Defect: Location: Paint to ma Defect: Location: to basemen	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other
Requirement: Comments: Component: Requirements: Comments: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code	Location: Defect: Location: Paint to ma Defect: Location: to basemen	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Replace and repair sections of soffit that a Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-parts of roof that may be compromised with	Location:  Defect: Location: Paint to ma  Defect: Location: to basementh like mate	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other rials.
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-	Location: Defect: Location: Paint to ma Defect: Location: to basemen	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Replace and repair sections of soffit that a Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-parts of roof that may be compromised with	Location:  Defect: Location: Paint to ma  Defect: Location: to basementh like mate	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other rials.
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-parts of roof that may be compromised with  Accessory Buildings	Defect: Location: Paint to ma  Defect: Location: to basementh like mate  Defect: Location:	Main Structure Throughout Paint to match.  Severly peeling paint Main Structure Throughout atch.  Holes or major defect Main Structure Throughout t access. Repair any other rials.  See Comments
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean- parts of roof that may be compromised with  Accessory Buildings  The shed in its current condition does not of the primary structure is demolished and not	Location: re missing.  Defect: Location: Paint to ma  Defect: Location: to basementh like mate Defect: Location: constitute a primary sti	Main Structure Throughout Paint to match.  Severly peeling paint  Main Structure Throughout atch.  Holes or major defect  Main Structure Throughout t access. Repair any other rials.  See Comments  public nuisance. However, if ructure is immediately built on
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code  Replace and repair sections of soffit that a  Windows/Window Frames Complaince with Int Residential Code  Scrap and paint any windows and frames.  Roof Complaince with Int Residential Code  Repair hole with proper materials on lean-parts of roof that may be compromised with Accessory Buildings  The shed in its current condition does not design.	Defect: Location: Defect: Location: to basement like mate Defect: Location: to basement like mate dependent of the like mate constitute a primary still as well be	Main Structure Throughout Paint to match.  Severly peeling paint  Main Structure Throughout atch.  Holes or major defect  Main Structure Throughout t access. Repair any other rials.  See Comments  public nuisance. However, if ructure is immediately built on caused it is an accessory use

# **Polk County Assessor**

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3886 polkweb@assess.co.polk.ia.us


	Location												
Address	2513 WOODLAND AVE												
City	DES MOINES	Zip	50312	Jurisdiction	Des Moines								
District/Parcel	030/05575-000-000	Geoparcel	7824-05-307-013	Status	<u>Active</u>								
School	Des Moines	Nbhd/Pocket	DM93/Z	Tax Authority Group	DEM-C- DEM-77131								
Submarket	Northwest Des Moines	Appraiser	Mark Patterson, CAE, CCIM, ICA 515-286-3148										

## Map and Current Photos - 1 Record



WOODLANDAVE

Bigger Map Polk County GIS
Google Map Pictometry



## **Historical Photos**

Ownership - 1 Record										
Ownership Num Name Recorded Book/Page										
Title Holder	1	THOMAS, HARLAN HOWARD								
	Company of the Control of the Contro			A CONTRACTOR OF THE PROPERTY OF THE PARTY OF						

# **Legal Description and Mailing Address**

E 37 F LOT 24 WOODLAND PLACE

HARLAN HOWARD THOMAS 1425 IDAHO ST DES MOINES, IA 50316-2423


#### **Current Values**

Type	Class	Kind	Land		Bldg	Total				
2020 Value	Commercial	Full	\$4,500	\$1	16,100	\$20,600				
<u>Unadjusted Cost Report</u>										
		Zoning - 1 Re	ecord							
Zoning	Descri	SF	Asse	essor Zoning						
R1-60	One Family, Low Density R		R	esidential						

City of Des Mo	oines Com	munity I	Development	•	g and Urban .		515 283-418	32 (	(2012-03-20)
				Land	I				
Square Fe	et	1,850		Acres	0.042		Frontage	37	
Dep	th	50.0	Тор	ography	Blank		Shape		Rectangle
Vacano	ey	Blank	ank Unbu		Blank			J	
			Com	mercial S	Summary			- Marian Barrier	- Windows St. Market St. St. St. St. St. St. St. St. St. St
Occupancy	Retai	1	Age, Weighted		1913	3	Total Stor Heigh		
Land Area	1,850	) (	Gross Area		685	5 Fi	inished Are	a	685
Unfinished Bsmt Area	600	)	Finished Bsmt Area		(	)	Number o		0
Primary Group	- 1		Percent Primary Group		53.31	L	Percent Secondary Group		0.00
Grade, Weighted	5/Grade		Bldg Class, Weighted	1	ame, Concrete k, Tile, Tilt Up	1	Condition Weighte		BN/Below Normal
Ground Floor Area	685		Perimeter		110	)			
			Commerc	cial Sectio	ons - 1 Record	1			
			Comn	nercial Se	ction #101	WILLIAM STATE OF THE STATE OF T			
Section Multiplier		1	Occu	pancy	Retail	Four	ndation	Со	ncrete Block or Tile
Exterior Wall	Siding	/Shingle	Insu	lation	Yes		Roof		Gable
Roof Material		Shingle	V	Viring	Adequate	Plu	ımbing		Adequate
Total Story Height		1	Frame	е Туре	Frame	Bld	g Class	C	Frame, Concrete Blk, Tile, Tilt Up
Total Section Area		1,285		round Area	685	Per	imeter		110
Grade		5+00	Year	Built	1913	R	Year emodel		1970
Condition									
Comment	A=1S	FR/BSM	IT B=1S FR		•				

UPB

	Commercial Groups - 2 Records												
Commercial Group #101 1													
Use Code	Retail Small	Base Story	1	Number Stories	1								
Total Group Area	685	Base Floor Area	685	Heating	Central								
Air Conditioning	Yes	Exhaust System	No										
	Co	mmercial Group	#101 2										
Use Code	Basement Entire	Number Stories	1	Total Group Area	600								
Base Floor Area	600	Heating	None	Air Conditioning	None								
Exhaust System	No												



Parmite	75	10	T
PARIMITE		11-2	

Year	Туре	Permit Status	Application	Reason	Reason1
2017	Pickup	No Add	2016-06-14	Review Value	CHECK CONDITION

Historical Values

	Yr	Туре	Class	Kind	Land	Bldg	Total
--	----	------	-------	------	------	------	-------

Yr	Туре	Class	Kind	Land	Bldg	Total
2019	Assessment Roll	Commercial	Full	\$4,500	\$16,100	\$20,600
2017	Assessment Roll	Commercial	Full	\$4,500	\$14,800	\$19,300
2015	Assessment Roll	Commercial	Full	\$3,700	\$14,100	\$17,800
2013	Assessment Roll	Commercial	Full	\$3,700	\$13,000	\$16,700
2011	Assessment Roll	Commercial	Full	\$3,700	\$13,000	\$16,700
2009	Assessment Roll	Commercial	Full	\$3,700	\$13,000	\$16,700
2007	Assessment Roll	Commercial	Full	\$3,700	\$14,600	\$18,300
2005	Assessment Roll	Commercial	Full	\$3,300	\$14,200	\$17,500
2003	Assessment Roll	Commercial	Full	\$2,900	\$13,300	\$16,200
2001	Assessment Roll	Commercial	Full	\$2,780	\$12,500	\$15,280
1999	Assessment Roll	Commercial	Full	\$2,900	\$12,500	\$15,400
1995	Assessment Roll	Commercial	Full	\$2,800	\$12,100	\$14,900
1993	Assessment Roll	Commercial	Full	\$2,700	\$11,500	\$14,200
1991	Assessment Roll	Commercial	Full	\$2,590	\$11,010	\$13,600
1991	Was Prior Year	Commercial	Full	\$2,590	\$10,280	\$12,870

This template was last modified on Sat Mar 4 12:31:48 2017 .