Roll Cal	I Num	ıber			Agenda Item Number
Date Februa	ary 22, 2	2021			
	ABA	TEME	NT OF	F PUBL	IC NUISANCES AT 1006 E LACONA AVENUE
inspected b	y repres	sentativ their p	es of th resent	ne City o	ed at 1006 E Lacona Avenue, Des Moines, Iowa, was of Des Moines who determined that the main structure and on constitutes not only a menace to health and safety but
Mortgage	Holder,	United	Bank	of Iow	Raymond A. Gardner and Margaret J. Gardner, and va, were notified more than thirty days ago to repair or ge structure and as of this date have failed to abate the
NOW THI MOINES,		RE, BE	IT RI	ESOLV	ED BY THE CITY COUNCIL OF THE CITY OF DES
MAPLETO	ON, an (Official	Plat, n	ow inch	structure on the real estate legally described as Lot 2 in uded in and forming a part of the City of Des Moines, Polk 06 E Lacona Avenue, have previously been declared public
a decree or nuisances,	rdering as order	the abatred, that	tement t the m	of the patter ma	ereby authorized to file an action in district court to obtain public nuisances, and should the owner(s) fail to abate the may be referred to the Department of Engineering which will and remove said structures.
					Moved byto adopt.
FORM AF	PROVI	ED:			
<u>/s/ Mega</u> Megan No				Attorne	у
COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, P. Kay Cmelik, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among
GRAY					other proceedings the above was adopted

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
GATTO				
GRAY				
MANDELBAUM				
VOSS				
WESTERGAARD				
TOTAL				
MOTION CARRIED	•		APP	ROVED

Mayor

other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

City C




Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

Location							
Address	Address 1006 E LACONA AVE						
City	DES MOINES	Zip	50315	Jurisdiction	Des Moines		
District/Parcel	010/03292-000-000	Geoparcel	7824-15-278-011	Status	<u>Active</u>		
School	Des Moines	Nbhd/Pocket	DM25/Z	Tax Authority Group	DEM-C-DEM- 77131		
Submarket	South Des Moines	Appraiser	Andrew Rand 515- 286-3368				

Map and Current Photos - 1 Record

Click on parcel to get a new listing



Bigger Map Polk County GIS
Google Map Pictometry

Historical Photos

Ownership - 2 Records							
Ownership Num Name Recorded Book/Pag							
1	GARDNER, RAYMOND A	2011-05-17	<u>13853/562</u>				
2	GARDNER, MARGARET J						
	Num 1 2	Num Name 1 GARDNER, RAYMOND A	NumNameRecorded1GARDNER, RAYMOND A2011-05-17				

Legal Description and Mailing Address

LOT 2 MAPLETON

RAYMOND A GARDNER 501 R AVE PATON, IA 50217-8019

Current Values

Type	Class	Kind	Land	Bldg	Total
2020 Value	Residential	Full	\$12,000	\$78,100	\$90,100

Market Adjusted Cost Report

Auditor Adjustments to Value

Category	Name	Information
	GARDNER, MARGARET J	Application #32920

Zoning - 1 Record


Zoning - 1 Record							
Zoning	Description	SF	Assessor Zoning				
N3B	N3b Neighborhood District		Residential				
City of Des Moines Community Development Planning and Urban Design 515 283-4182 (2012-03-20)							
City of Des induites Community Development							

Land

					50.0
Square Feet	6,000	Acres	0.138	Frontage	50.0
Depth	120.0	Topography	Normal	Shape	Rectangle
		Unbuildable	No		
Vacancy	No	A C A C			

Residences - 1 Record

Residence #1						
Occupancy	Single Family	Residence Type	1 Story Finished Attic	Building Style	Conventional	
Year Built	1908	Number Families	1	Grade	5+10	
Condition	Normal	Total Square Foot Living Area	1368	Main Living Area	1013	
Attic Finished Area	355	Basement Area	725	Open Porch Area	54	
Deck Area	348	Foundation	Masonry	Exterior Wall Type	Stucco	
Roof Type	Gable	Roof Material	Asphalt Shingle	Heating	Gas Forced Air	
Air Conditioning	0	Number Bathrooms	1	Bedrooms	2	
Rooms	6					



Detached Structures - 1 Record

Detached Structure #101								
Occupancy Garage Construction Type Frame Measurement Code Dimensions								
Measure 1	24	Measure 2	30	Story Height	1			
Grade	4	Year Built	1990	Condition	Normal			
Graue	-	Total Bulle						

Sales - 1 Record

Seller	Buyer	Buyer Sale Date		Instrument	Book/Page
KEUL, J MELVIN	GARDNER, RAYMOND A	1989-08-24	\$33,000	Contract	6140/488

Permits - 3 Records

Year	Type	Permit Status	Application	Reason	Reason1
1995	Permit	Complete	1994-04-08		Wood Deck
1992	Permit	Complete	1990-04-13		New Garage
1992	Permit	Partial	1990-04-13		New Garage

Historical Values

Vr	Tyma	Class	Kind	Land	Bldg	Total
2019	Type Assessment Roll	Residential	Full	\$12,000	\$78,100	\$90,100
			Full	\$10,800	\$73,300	\$84,100
2017	Assessment Roll	Residential	1 un	Φ10,000	Ψ, υ, υ σ	

Yr	Туре	Class	Kind	Land	Bldg	Total
2015	Assessment Roll	Residential	Full	\$10,100	\$70,100	\$80,200
2013	Assessment Roll	Residential	Full	\$9,700	\$68,900	\$78,600
2011	Assessment Roll	Residential	Full	\$9,700	\$70,300	\$80,000
2009	Assessment Roll	Residential	Full	\$10,000	\$72,200	\$82,200
2007	Assessment Roll	Residential	Full	\$10,400	\$69,300	\$79,700
2005	Assessment Roll	Residential	Full	\$11,300	\$62,900	\$74,200
2003	Assessment Roll	Residential	Full	\$10,430	\$57,920	\$68,350
2001	Assessment Roll	Residential	Full	\$6,550	\$53,160	\$59,710
			Adj	\$6,550	\$45,320	\$51,870
1999	Assessment Roll	Residential	Full	\$8,310	\$44,250	\$52,560
			Adj	\$8,310	\$36,410	\$44,720
1997	Assessment Roll	Residential	Full	\$7,550	\$40,190	\$47,740
			Adj	\$7,550	\$32,350	\$39,900
1995	Assessment Roll	Residential	Full	\$6,800	\$36,200	\$43,000
1,,,,			Adj	\$6,800	\$28,360	\$35,160
1993	Assessment Roll	Residential	Full	\$6,240	\$31,120	\$37,360
1775			Adj	\$6,240	\$23,280	\$29,520
1992	Assessment Roll	Residential	Full	\$5,830	\$29,080	\$34,910
1991	Assessment Roll	Residential	Full	\$5,830	\$28,600	\$34,430
1991	Was Prior Year	Residential	Full	\$5,830	\$24,300	\$30,130

This template was last modified on Sun Jan 31 22:36:22 2021.



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: August 24, 2020

DATE OF INSPECTION:

February 03, 2020

CASE NUMBER:

COD2020-00844

PROPERTY ADDRESS:

1006 E LACONA AVE

LEGAL DESCRIPTION:

LOT 2 MAPLETON

RAYMOND A GARDNER Title Holder 501 R AVE PATON IA 50217-8019

UNITED BANK OF IOWA Mortgage Holder - OWN BOLTE, PRESIDENT 1609 HAWKEYE DR BOONE IA 50036

MARGARET J GARDNER Title Holder 501 R AVE PATON IA 50217-8019

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Neighborhood Inspection Division

(515) 283-4046

Nid Inspector

DATE MAILED: 8/24/2020

MAILED BY: TSY

Areas that need attention: 1006 E LACONA AVE

Component:	Soffit/Facia/Trim	Defect:	Deteriorated
Requirement:	Complaince with Int Residential Code		
ixequil cilicite	complained with the residential code	Location	Garage Throughout
		LUCACIUII.	Garage Throughout
Comments:	need to repair, replace scrap and to paint	o match an	v soffit fascia, or trim
	need to repair, replace scrap and to paint	o materian	y somerascia, or ann
Commonante	Chinales Fleshing	Defect:	Deteriorated
Component:	Shingles Flashing	Delecti	Deteriorated
<u>Requirement:</u>	Complaince with Int Residential Code		
		Location:	Roof
Comments:			sized areas with matching
	replace with one layer of shingles or repla	ce compron	ilsed areas with matching
	material		
Component:	Roof	Defect:	Deteriorated
Requirement:	Complaince with Int Residential Code		
	•	Location:	Main Structure
Comments:			
Comments	any deteriorated sheething needs to be re	placed	
Component:	Roof	Defect:	In poor repair
Requirement:	Complaince with Int Residential Code		•
Requirement	Complaince with the Residential Code	Location:	Main Structure
		Location	Main Sci decare
Comments:	downspouts and gutters need cleaned and	d repaired	
	downspoud and gatters need eleanes and		
ł			
1			
Component	Exterior Walls	Defect:	In disrepair
Component:	Exterior Walls	Defect:	In disrepair
Component: Requirement:	Exterior Walls Complaince with Int Residential Code		
			In disrepair Main Structure Throughout
	Complaince with Int Residential Code	Location:	Main Structure Throughout
Requirement:		Location:	Main Structure Throughout
Requirement:	Complaince with Int Residential Code	Location:	Main Structure Throughout
Requirement:	Complaince with Int Residential Code	Location:	Main Structure Throughout
Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromise	Location:	Main Structure Throughout rwashed
Requirement: Comments: Component:	Complaince with Int Residential Code siding needs repaired where compromise Foundation	Location:	Main Structure Throughout
Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromise	Location: d and power Defect:	Main Structure Throughout rwashed Cracked/Broken
Requirement: Comments: Component:	Complaince with Int Residential Code siding needs repaired where compromise Foundation	Location: d and power Defect:	Main Structure Throughout rwashed
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code siding needs repaired where compromise Foundation Complaince with Int Residential Code	Location: d and power Defect: Location:	Main Structure Throughout rwashed Cracked/Broken Unknown
Requirement: Comments: Component:	Complaince with Int Residential Code siding needs repaired where compromise Foundation Complaince with Int Residential Code need to repair cracked and loose foundation	Location: d and power Defect: Location:	Main Structure Throughout rwashed Cracked/Broken Unknown
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code siding needs repaired where compromise Foundation Complaince with Int Residential Code	Location: d and power Defect: Location:	Main Structure Throughout rwashed Cracked/Broken Unknown
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code siding needs repaired where compromise Foundation Complaince with Int Residential Code need to repair cracked and loose foundation	Location: d and power Defect: Location:	Main Structure Throughout rwashed Cracked/Broken Unknown
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised	Location: d and power Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if
Requirement: Comments: Component: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim	Location: d and power Defect: Location:	Main Structure Throughout rwashed Cracked/Broken Unknown
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou
Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou
Requirement: Comments: Requirement: Comments: Comments: Comments: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou
Requirement: Comments: Component: Requirements: Comments: Comments: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace, scrap and paint to	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code	Location: Defect: Location: ion may nee	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace, scrap and paint to	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace, scrap and paint to	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace,scrap and paint to Exterior Walls Complaince with Int Residential Code	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace,scrap and paint to Exterior Walls Complaince with Int Residential Code	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace, scrap and paint to	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim
Requirement: Comments: Component: Requirement: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code siding needs repaired where compromises Foundation Complaince with Int Residential Code need to repair cracked and loose foundat structure is compromised Soffit/Facia/Trim Complaince with Int Residential Code need to repair, replace,scrap and paint to Exterior Walls Complaince with Int Residential Code	Location: d and power Defect: Location: ion may nee Defect: Location: o match any	Main Structure Throughout rwashed Cracked/Broken Unknown ed a final building permit if Deteriorated Accessory Building Throughou soffit, fascia, or trim

1006 E Lacona Aue





70P

1006 E Lacona Ave

