

.....

Date <u>March 22, 2021</u>

ABATEMENT OF PUBLIC NUISANCE AT 818 E. 27TH ST.

WHEREAS, the property located at 818 E. 27th St., Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, L & R Real Estate LLC, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot One (1) in Block "C" in EAST PARK PLACE, now included in and forming a part of the City of Des Moines, except the East 50 feet thereof; and the North 70 feet of Lot Five (5), of the Official Plat of the Northeast 1/4 of Section 2, Township 78, Range 24, West of the 5th P.M., Iowa, now included in and forming a part of the City of Des Moines, Polk County, Iowa except the East 50 feet thereof, and locally known as 818 E. 27th St., has previously been declared a public nuisance;

The City Legal Department, through special counsel Ahlers & Cooney, P.C., is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM	A AP	PROV	ED:		
21	= A	15	\mathcal{A}	AL	

Kristine Stone, Special Counsel Ahlers & Cooney, P.C.

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
GATTO				
GRAY				
MANDELBAUM				
VOSS				
WESTERGAARD				
TOTAL				
MOTION CARRIED	·		API	PROVED

CERTIFICATE

I, P. Kay Cmelik, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

Mayor

City Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: January 4, 2	2021	DATE OF INSPECTION:	May 19, 2020
CASE NUMBER:	COD2020-02623		
PROPERTY ADDRESS:	818 E 27TH ST		
LEGAL DESCRIPTION:	LOT 20 BLK 2 FARWELL PLACE		

ANA M MURUETA ESPINOZA Title Holder 825 E 27TH ST DES MOINES IA 50317

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES. Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Kevin Pyles

(515) 283-4122

Nid Inspector

DATE MAILED:

1/4/2021

MAILED BY: JDH

Mechanical System Mechanical Permit Gas service has been shut off need licensed mechar mechanical systems and correct any violations prior required. Electrical System Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu plumbing permit.	to service be Defect: Location: electrical sys Defect: Location: Il violations n	In poor repair Main Structure Throughout Stem and correct any In poor repair Main Structure Throughout Main Structure Throughout
Gas service has been shut off need licensed mechar mechanical systems and correct any violations prior required. Electrical System Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	Defect: Location: Defect: Location: electrical sys Defect: Location: Il violations n	Main Structure Throughout or to verify safety of eing restored. Permit In poor repair Main Structure Throughout stem and correct any In poor repair Main Structure Throughout meed to be corrected
mechanical systems and correct any violations prior required. Electrical System Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	Defect: Location: Defect: Location: electrical sys Defect: Location: Il violations n	or to verify safety of eing restored. Permit In poor repair Main Structure Throughout stem and correct any In poor repair Main Structure Throughout need to be corrected
mechanical systems and correct any violations prior required. Electrical System Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	to service be Defect: Location: electrical sys Defect: Location: Il violations n	In poor repair Main Structure Throughout Stem and correct any In poor repair Main Structure Throughout Main Structure Throughout
Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	Location: electrical sys Defect: Location: Il violations n	Main Structure Throughout stem and correct any In poor repair Main Structure Throughout need to be corrected
Electrical Permit Hire licensed electrical contractor to verify safety of violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	electrical sys Defect: Location: Il violations n	In poor repair Main Structure Throughout need to be corrected
violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	electrical sys Defect: Location: Il violations n	In poor repair Main Structure Throughout need to be corrected
violations that may exist. Plumbing System Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	Defect: Location: Il violations n	In poor repair Main Structure Throughout need to be corrected
Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	Location:	Main Structure Throughout need to be corrected
Plumbing Permit Have plumbing system checked for any defects. A prior to utility being restored. Any repairs to the plu	II violations n	need to be corrected
prior to utility being restored. Any repairs to the plu	II violations n	need to be corrected
prior to utility being restored. Any repairs to the plu		
Interior Walls /Ceiling	Defect:	Missing
Building Permit		
	Location:	Main Structure Throughout
Repair/replace any rotted, damaged or broken boar will require a building permit.	rds. Any repa	irs to the structure
Interior Walls /Ceiling	Defect:	Missing
Compliance, International Property		
Maintenance Code	Location:	Main Structure Throughout
		v frames. Any
Exterior Walls	Defect:	In poor repair
Maintenance Code	Location:	Main Structure Throughout
Repair/replace any broken, missing , damaged or restructure will require a building permit.	otted siding.	Any repairs to the
Soffit/Facia/Trim	Defect:	In poor repair
		F
Maintenance Code	Location:	Main Structure Throughout
Repair/replace any rotted, damaged or broken boa will require a building permit.	rds. Any repa	airs to the structure
Soffit/Facia/Trim	Defect:	Absence of paint
	Location:	Main Structure Throughout
	Building Permit Repair/replace any rotted, damaged or broken boar will require a building permit. Interior Walls /Ceiling Compliance, International Property Maintenance Code Repair/replace any missing, rotted or damaged win repairs to the structure will require a building perm Exterior Walls Compliance, International Property Maintenance Code Repair/replace any broken, missing , damaged or r structure will require a building permit. Soffit/Facia/Trim Compliance, International Property Maintenance Code Repair/replace any rotted, damaged or broken boa will require a building permit. Soffit/Facia/Trim Compliance, International Property Maintenance Code Repair/replace any rotted, damaged or broken boa will require a building permit.	Building Permit Location: Repair/replace any rotted, damaged or broken boards. Any repawill require a building permit. Defect: Interior Walls /Ceiling Defect: Compliance, International Property Maintenance Code Location: Repair/replace any missing, rotted or damaged windows/window repairs to the structure will require a building permit. Defect: Compliance, International Property Maintenance Code Location: Exterior Walls Defect: Compliance, International Property Maintenance Code Location: Repair/replace any broken, missing , damaged or rotted siding. structure will require a building permit. Soffit/Facia/Trim Defect: Soffit/Facia/Trim Defect: Compliance, International Property Maintenance Code Location: Repair/replace any broken, missing , damaged or rotted siding. Soffit/Facia/Trim Defect: Compliance, International Property Maintenance Code Location: Repair/replace any rotted, damaged or broken boards. Any repair will require a building permit. Soffit/Facia/Trim Defect: Compliance, International Property Maintenance Code Location: Compliance, International Property Maintenance Code

Areas that need attention: 818 E 27TH ST

Polk County Assessor 050/01232-000-000

Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

				Locatio	n				
Address	818 E 27TH	ST							
City	DES MO	OINES	Zi	p	50317	Jurisdiction	Des Moines		
District/Parcel	050/01232-0	00-000	Geoparcel 7824-01-202-016		Status	Active			
School					DM16/Z	Tax Authority Group	DEM-C-DEM- 77131		
Submarket	Northeast Des	s Moines	Appraise	er B	raxton Peats 515- 286-3839				
		I	Map and C	urrent	Photos - 1 Reco	ord			
Clic	k on parcel to	get a ne	ew listing						
901		830	901		Ph	oto Processed on 2	010-10-14 a		
825		828	825	1		1 and	a Mass		
821		824	823				1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		
819 818 TH 817									
815		814							
	1 1						CONTRACTOR AND CONTRACTOR		
	igger Map Po				<u>)</u>				
	l l igg <u>er Map</u> Po <u>Google Map</u>	l <u>lk Count</u> <u>Pictome</u>	<u>etry</u>	listorics	1 Photos				
			<u>etry</u> H		1 Photos				
	<u>Google Map</u>		<u>etry</u> <u>H</u> Owner	rship -	l Photos 1 Record	Recorded	Book/Page		
Ownership	Google Map Num	Pictom	<u>etry</u> H Owner N	rship - Name	1 Record	Recorded 2017-08-18	Book/Page 16611/61		
	<u>Google Map</u>	Pictome MUR	etry H Owner N UETA ESP	rship - Vame INOZA	1 Record	2017-08-18	Book/Page <u>16611/61</u>		
Ownership Title Holder	Google Map Num 1	Pictome MUR Leg	etry <u>H</u> Owner N UETA ESP al Descripti	rship - Vame INOZA	1 Record ., ANA M I Mailing Addr ANA M MU	2017-08-18 ess RUETA ESPINOZA	<u>16611/61</u>		
Ownership	Google Map Num 1	Pictome MUR Leg	etry <u>H</u> Owner N UETA ESP al Descripti	rship - Vame INOZA	1 Record , ANA M I Mailing Addr	2017-08-18 ess RUETA ESPINOZA ST	<u>16611/61</u>		
Ownership Title Holder	Google Map Num 1	Pictome MUR Leg	etry <u>H</u> Owner N UETA ESP al Descripti	rship - Vame INOZA	1 Record , ANA M I Mailing Addr ANA M MU 814 E 27TH DES MOINE	2017-08-18 ess RUETA ESPINOZA ST	<u>16611/61</u>		
Ownership Title Holder	Google Map Num 1	Pictome MUR Leg	etry <u>H</u> Owner N UETA ESP al Descripti	rship - Name INOZA ion and	1 Record , ANA M I Mailing Addr ANA M MU 814 E 27TH DES MOINE	2017-08-18 ess RUETA ESPINOZA ST S, IA 50317 Bldg	<u>16611/61</u>		

2020 Value Residential Full \$17,100 \$36,000 \$53,100									
	Market Adjusted Cost Report								
Zoning - 1 Record									
Zoning Description SF Assessor Zoning									
N3C N3c Neighborhood District Residential									
City of Des Me	City of Des Moines Community Development Planning and Urban Design 515 283-4182 (2012-03-20)								

web.assess.co.polk.ia.us/cgi-bin/web/tt/infoqry.cgi?tt=card/card&dp=05001232000000&

3/2/2021

Polk County Assessor 050/01232-000-000

Square Feet6,950Acres0.160Frontage50.0Depth139.0TopographyNormalNormalShapeRectangleVacancyNoUnbuildableNoNormalShapeRectangleVacancyNoUnbuildableNoNormalShapeRectangleResidences - I RecordResidence Type1 StoryBuilding StyleBungalowYear Built1921Number Families1Grade5+05ConditionBelow NormalTotal Square Foot Living Area828 AreaMain Living Area828 Area100Basement Area238Enclosed Porch Area32 Forced AreaGas Forced AirAir Conditioning Air100Roof MaterialAsphalt ShingleHeating ShingleGas Forced AirAir Conditioning Air100			Land						
Depth139.0TopographyNormalShapeRectangleVacancyNoUnbuildableNoNoResidences - 1 RecordResidence #1OccupancySingle FamilyResidence Type1 StoryBuilding StyleBungalowYear Built1921Number Families1Grade5+05ConditionBelowTotal Square Foot Living Area82.8Main Living Area82.8Basement Area238Enclosed Porch Area32Deck Area122FoundationBrickExterior Wall TypeHardboardRoof TypeGableRoof MaterialShingleHeatingForced AirConditioning100Number Bathrooms1Bedrooms2Rooms4Image: start	Square Feet	6,950	Acres	0.160	Frontage	50.0			
Vacancy No Unbuildable No Residences - 1 Record Residence #1 Occupancy Single Family Residence Type 1 Story Building Style Bungalow Year Built 1921 Number Families 1 Grade 5+05 Condition Below Total Square Foot 828 Main Living 8228 Basement Area 238 Enclosed Porch 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Asphalt Heating Forced Air Conditioning 100 Number 1 Bedrooms 2 Rooms 4 Bathrooms 1 Bedrooms 2 Rooms 4				Normal		Rectangle			
Residence #/1 Occupancy Year Built Single Family Residence Type 1 Story Building Style Bungalow Vear Built 1921 Number Families 1 Grade 5+02 Condition Below Total Square Foot 828 Main Living Area 828 Basement Area 238 Enclosed Porch Area 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Material Shingle Heating Forced Aria Air Conditioning 100 Number Bathrooms 1 Bedrooms 2 Rooms 4				No					
Occupancy Single Family Residence Type 1 Story Building Style Bungalow Vear Built 1921 Number Families 1 Grade 5+05 Condition Below Total Square Foot Normal 828 Main Living Area 828 Basement Area 238 Enclosed Porch Area 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Material Shingle Heating Gras Forced Air Air 100 Number Bathrooms 1 Bedrooms 2 Rooms 4			Residences -	1 Record					
Occupancy Family Residence Type 1 Story Style Bullgatow Year Built 1921 Number Families 1 Grade 5+05 Condition Below Total Square Foot 828 Main Living Area 828 Basement 238 Enclosed Porch 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Asphalt Heating Gras Air Air Number 1 Bedrooms 2 Rooms 4 Number 1 Bedrooms 2 Rooms 4			Residence	e #1					
Condition Below Normal Total Square Foot Living Area 828 Main Living Area 828 Basement Area 238 Enclosed Porch Area 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Asphalt Shingle Heating Gas Forced Air Air Conditioning 100 Number Bathrooms 1 Bedrooms 2 Rooms 4	Occupancy	Single Family		1 Story					
Condition Normal Living Area 0.20 Area 0.22 Basement Area 238 Enclosed Porch Area 32 Deck Area 120 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Asphalt Material Shingle Heating Forced Air Air Conditioning 100 Number Bathrooms 1 Bedrooms 2 Rooms 4 12 10 10 100 100 100 12 10 100 100 100 100 13 Bedrooms 2 Rooms 4 14 10 100 100 100 15 10 100 100 100 14 10 100 100 100 100 15 10 100 100 100 100 100 14 10 100 100 100 100 100 100 12 10 100 100 100 100 100 100<	Year Built					5+05			
Area 238 Area 32 Deck Area 12 Foundation Brick Exterior Wall Type Hardboard Roof Type Gable Roof Asphalt Heating Gas Air Conditioning 100 Number 1 Bedrooms 2 Rooms 4 Stingle 1 Bedrooms 2 Rooms 4	Condition		Living Area	828		828			
Roof Material Asphalt Shingle Heating Gas Forced Air Air Conditioning 100 Number Bathrooms 1 Bedrooms 2 Rooms 4 i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i i		238	Area			1			
Koot Material Aspnant Shingle Heating Forced Air Air Conditioning 100 Number Bathrooms 1 Bedrooms 2 Rooms 4	Foundation	Brick	Exterior Wall Type	Hardboard	Roof Type	Gable			
Bathrooms 1 Bedrooms 2 Rooms 2 Bathrooms 1 10 10 10 9rc Poresto 4 10 10 12 12 12 12 8 10 10 10 10 10 10 10 10 11 10 12 12 10 10 10 10			Heating	Forced		100			
$\begin{bmatrix} y \\ y $		1	Bedrooms	2	Rooms	4			
		12	13 Bsmt 327 744	20 12 1s 7 84 7	34				

Sales - 3 Records

2

٦D

3/2/2021

Polk County Assessor 050/01232-000-000

Seller	Buyer	Buyer Sale Date		Instrument	Book/Page
ELDON WOLTZ TRUST	MURUETA ESPINOZA, ANA M	<u>2017-08-18</u>	\$10,000	Deed	<u>16611/61</u>
ELDON WOLTZ, TRUST	WISEMAN, DIANE	<u>1997-02-28</u>	\$37,500	Contract	<u>7585/358</u>
CLOVER, JEFFREY D	ELDON WOLTZ TRUST	<u>1995-08-07</u>	\$15,000	Deed	<u>7242/83</u>

Recent Ownership Transfers

Granto)r	Grantee		Instrume Date	ent	Reco Date	8		strument pe	Book/Pg	
WOLT PETER (Truste ELDOI WOLT	e)	MURUETA ESPINOZA, ANA M		ESPINOZA,		ESPINOZA, 2017-08-18 2017-08-		-08-	W	ustee arranty ed	<u>16611/61</u>
Former Known WISE DIANE COWL	As MAN, E 	ELDON WOLTZ TRUST		2016 2 14		2017 10			rfeiture Contract	<u>16339/762</u>	
DIANE	3										
				Permits							
Year	Туре	Permit Status			plicat	tion	on Reas			leason1	
1989	Permit	Complete		1988-0	6-17				Demolish Garage		
				Historie	cal Va	alues					
Yr	Туре		Class		K	ind	La	nd	Bldg		
2019	Assessm	nent Roll	Resid					00	\$36,000		
2017		nent Roll	Resid			Full	\$14,700		\$31,400		
2015		nent Roll	Resid			Full	\$13,7		\$29,200		
2013		nent Roll	Resid			Full	\$13,7		\$29,600		
2011		nent Roll	Resid			Full	\$15,6		\$33,600		
2009		nent Roll	Resid			Full	\$16,5		\$35,800		
2007		nent Roll	Resid			Full	\$16,300		\$35,400		
2005		nent Roll	Resid				\$15,000		\$34,000		
2003		nent Roll				\$12,800 \$29,630					
2001		nent Roll	Resid			Full \$12,57			\$30,260		
1999		nent Roll	Resid			Full\$7,690Full\$6,970			\$24,850		
1997		nent Roll		Residential		Full			\$22,510		
1995		nent Roll	Resid			Full	\$6,0		\$19,600 \$17,380		
1993		nent Roll	Resid			Full Full	\$5,3		\$17,380		
1990	Board A	nent Roll	Resid			Full	\$5,3 \$5,3		\$14,620		
1990 1989			Resid			Full	\$5,3		\$10,520		
1909	ASSESSI	essment Roll Res		ontial	. · ·	I ull	φ.σ,σ	00	ψ1-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ψ20,510	

STD

This template was last modified on Sun Jan 31 22:36:22 2021.





