

.....

Date May 24, 2021

# ABATEMENT OF PUBLIC NUISANCE AT 818 E. 27<sup>TH</sup> ST.

WHEREAS, the property located at 818 E. 27th St., Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Ana M. Murueta Espinoza, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 20 in Block Two (2) in Farwell Place, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 818 E. 27th St., has previously been declared a public nuisance;

The City Legal Department, through special counsel Ahlers & Cooney, P.C., is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by to adopt.

FORM APPROVED:

Kristine Stone, Special Counsel Ahlers & Cooney, P.C.

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, P. Kay Cmelik, City Clerk of said City herek
GATTO					certify that at a meeting of the City Council of sai
GRAY					City of Des Moines, held on the above date, amor other proceedings the above was adopted.
MANDELBAUM					other proceedings the above was adopted.
VOSS			IN WITNESS WH	IN WITNESS WHEREOF, I have hereunto set m	
WESTERGAARD					hand and affixed my seal the day and year fir
TOTAL					above written.
OTION CARRIED			API	PROVED	

Mayor

City Clerk



### PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: January 4, 2	2021	DATE OF INSPECTION:	May 19, 2020
CASE NUMBER:	COD2020-02623		
PROPERTY ADDRESS:	818 E 27TH ST		
LEGAL DESCRIPTION:	LOT 20 BLK 2 FARWELL PLACE		

ANA M MURUETA ESPINOZA Title Holder 825 E 27TH ST DES MOINES IA 50317

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

**Kevin Pyles** 

(515) 283-4122

Nid Inspector

DATE MAILED: 1/4

1/4/2021

MAILED BY: JDH

\\CDMAPPS1\D-VOLUME\APPDATA\Tidemark\prd\_41\Forms & Reports\dsmCODPubNo.rpt

Comments: Gas service has been shut off need licensed mechanical contractor to verify safety of mechanical systems and correct any violations prior to service being restored. Permit required.   Commonent: Electrical System Dafect: In poor repair   Requirement: Electrical Permit Location: Main Structure Throughe   Commonents: Hire licensed electrical contractor to verify safety of electrical system and correct any violations that may exist. Defect: In poor repair   Commonent: Plumbing System Defect: In poor repair   Requirement: Plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit.   Commonents: Interior Walls /Celling Defect: Missing   Requirement: Building Permit Location: Main Structure Throughe comments:   Commonents: Interior Walls /Celling Defect: Missing   Requirement: Complance, International Property Mains Structure Throughe complance, International Property   Maintenance Code Location: Main Structure Throughe complance, International Property   Maintenance Code Location: Main Structure Throughe Complance, International Property   Mai	eas that need atte	tention: 818 E 27TH ST		
Comments: Gas service has been shut off need licensed mechanical contractor to verify safety of mechanical systems and correct any violations prior to service being restored. Permit required.   Component: Electrical System Defect: In poor repair   Beauirement: Electrical Permit Location: Main Structure Throughe   Components: Hire licensed electrical contractor to verify safety of electrical system and correct any violations that may exist. Defect: In poor repair   Component: Plumbing System Defect: In poor repair   Requirement: Plumbing System Defect: Main Structure Throughe   Comments: Plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit. Location: Main Structure Throughe   Comments: Interior Walls /Celling Defect: Missing Requirement: Main Structure Throughe   Comments: Interior Walls /Celling Defect: Missing Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Throughe   Components: Interior Walls /Celling Defect: Main Structure Throughe   Requirement: Compliance, Inte		incentantical official	Defect:	Water/Gas/Electric
mechanical systems and correct any violations prior to service being restored. Permit required.   Component: Electrical System Defect: In poor repair   Requirement: Electrical Permit Location: Main Structure Throughe   Component: Plumbing System Defect: In poor repair   Component: Plumbing System Defect: In poor repair   Requirement: Plumbing System Defect: In poor repair   Requirement: Plumbing System Defect: Main Structure Throughe   Comments: Plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit. Main Structure Throughe   Component: Interior Walls /Celling Defect: Missing   Requirement: Building Permit Location: Main Structure Throughe   Commonents: Interior Walls /Celling Defect: Missing   Requirement: Complance, International Property Main Structure Throughe   Component: Interior Walls /Celling Defect: Missing   Requirement: Complance, International Property Main Structure Throughe   Com	omments:			Main Structure Throughout
Requirement: Electrical Permit Location: Main Structure Through   Comments: Hire licensed electrical contractor to verify safety of electrical system and correct any violations that may exist. Defect: In poor repair   Comments: Plumbing System Defect: In poor repair   Requirement: Plumbing System checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit.   Commonent: Interior Walls /Celling Defect: Missing   Requirement: Building Permit Location: Main Structure Through   Commonent: Interior Walls /Celling Defect: Missing   Requirement: Complance, International Property Main Structure Through   Commonents: Interior Walls /Celling Defect: Missing   Requir/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Through   Commonents: Interior Walls /Celling Defect: Missing   Requir/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. In poor repair   Components: Exterior Walls Defect: In poor repair	n	mechanical systems and correct any violations prior		
Comments: Location: Main Structure Throughor violations that may exist.   Comments: Hire licensed electrical contractor to verify safety of electrical system and correct any violations that may exist. Defect: In poor repair   Requirement: Plumbing System Defect: In poor repair   Comments: Plumbing Permit Location: Main Structure Throughor comments:   Comments: Have plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit.   Comments: Have plumbing Permit Location: Main Structure Throughor comments:   Comments: Building Permit Location: Main Structure Throughor comments:   Comments: Building Permit Location: Main Structure Throughor comments:   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Through comments:   Comments: Interior Walls /Celling Defect: Main Structure Through comments:   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Any repairs to the structure Through comments:   Comments: Exterior Walls			Defect:	In poor repair
Hire licensed electrical contractor to verify safety of electrical system and correct any violations that may exist.   Component: Plumbing System   Requirement: Plumbing Permit   Location: Main Structure Throughe provide the plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit.   Component: Interior Walls /Celling Defect:   Building Permit Location: Main Structure Throughe contents:   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit.   Comments: Interior Walls /Celling Defect: Missing   Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Throughe Comments:   Commonent: Interior Walls /Celling Defect: Missing   Requir/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Commons:   Component: Exterior Walls Celling Defect: In poor repair   Comments: Exterior Walls Celling Location: Main Structure Through Maintenance Code   Commonent: Exterior Walls Cellin			Location:	Main Structure Throughout
Reauirement: Plumbing Permit Location: Main Structure Through   Comments: Have plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit. Interior Walls /Celling Defect: Missing   Comments: Interior Walls /Celling Defect: Missing   Requirement: Building Permit Location: Main Structure Throughe   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Throughe   Component: Interior Walls /Celling Defect: Missing   Requirement: Compliance, International Property Maintenance Code Location: Main Structure Throughe   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Defect: In poor repair   Compliance, International Property Maintenance Code Location: Main Structure Throughe   Complance, International Property Maintenance Code Location: Main Structure Throughe   Complance, International Property Maintenance Code Location: Main Structure Throughe   Complan	ŀ		electrical sys	item and correct any
Comments: Location: Main Structure Throughd   Comments: Have plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit. Interior Walls /Celling Defect: Missing   Comments: Interior Walls /Celling Defect: Missing   Requirement: Building Permit Location: Main Structure Throughd   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Throughd   Component: Interior Walls /Celling Defect: Missing   Requirement: Compliance, International Property Main Structure Throughd   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Main Structure Throughd   Comments: Exterior Walls Compliance, International Property Main Structure Throughd   Requirement: Compliance, International Property Main Structure Throughd Main Structure Throughd   Commonts: Exterior Walls Compliance, International Property Main Structure Throughd Main Structure Throughd   Comments: Soffit/Facia/Trim Defect		riambing eyeem	Defect:	In poor repair
Have plumbing system checked for any defects. All violations need to be corrected prior to utility being restored. Any repairs to the plumbing system will require a plumbing permit.   Component: Interior Walls /Ceiling Defect: Missing   Requirement: Building Permit Location: Main Structure Throughe   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit.   Component: Interior Walls /Ceiling Defect: Missing   Requirement: Compliance, International Property Main Structure Throughe   Maintenance Code Location: Main Structure Throughe   Component: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit.   Component: Exterior Walls Defect: In poor repair   Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Compliance, International Property Maintenance Code Location:   Maintenance Code Location: Main Structure Through   Compliance, International Property Maintenance Code Location:   Requirement: Soffit/Facia/Trim Defect:			Location:	Main Structure Throughout
Some of the structure will require a building permit. Location: Main Structure Througher of the structure will require a building permit.   Comments: Interior Walls /Celling Defect: Missing   Component: Interior Walls /Celling Defect: Missing   Requirement: Compliance, International Property Main Structure Througher   Maintenance Code Location: Main Structure Througher   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Defect: In poor repair   Component: Exterior Walls Defect: In poor repair Main Structure Througher   Component: Exterior Walls Defect: In poor repair   Compliance, International Property Main Structure Througher   Maintenance Code Location: Main Structure Througher   Compliance, International Property Maintenance Code Location: Main Structure Througher   Compliance, International Property Maintenance Code Location: Main Structure Througher   Compliance, International Property Maintenance Code Location: Main Structure Througher   Requirement: Soffit/Facia	۲ ۲	prior to utility being restored. Any repairs to the plu		
Comments:Location:Main Structure ThrougherComponent:Interior Walls /CeilingDefect:MissingRequirement:Compliance, International Property Maintenance CodeLocation:Main Structure ThrougherComponent:Exterior WallsCeilingDefect:MissingCompenent:Exterior WallsDefect:MissingMain Structure ThrougherComponent:Exterior WallsDefect:In poor repairComponent:Exterior WallsDefect:In poor repairComponent:Exterior WallsDefect:In poor repairRequirement:Compliance, International Property Maintenance CodeLocation:Main Structure ThrougherComponent:Exterior WallsDefect:In poor repairCompliance, International Property Maintenance CodeLocation:Main Structure ThrougherComments:Soffit/Facia/TrimDefect:In poor repairRepair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.In poor repairCompliance, International Property 			Defect:	Missing
Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit.   Component: Interior Walls /Ceiling Defect: Missing   Requirement: Compliance, International Property Location: Main Structure Through   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit.   Component: Exterior Walls Defect: In poor repair   Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Requirement: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Comments: Repair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.   Component: Soffit/Facia/Trim Defect: In poor repair   Compliance, International Property Main tenance Code Location: Main Structure Through   Component: Soffit/Facia/Trim Defect: In poor repair   Compliance, International Property Main Structure Through   Requirement: Soffit/Facia/Trim Defect:			Location:	Main Structure Throughout
Requirement: Compliance, International Property Main Structure Through   Comments: Repair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit. Defect: In poor repair   Component: Exterior Walls Defect: In poor repair   Comments: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Requirement: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Comments: Repair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.   Component: Soffit/Facia/Trim Defect: In poor repair   Requirement: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Requirement: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Requirement: Compliance, International Property Main Structure Through   Repair/replace any rotted, damaged or broken boards. Any repairs to			ds. Any repa	irs to the structure
Comments:Maintenance CodeLocation:Main Structure ThrougherRepair/replace any missing, rotted or damaged windows/window frames. Any repairs to the structure will require a building permit.Any repairs.Component:Exterior WallsDefect:In poor repairRequirement:Compliance, International Property Maintenance CodeLocation:Main Structure ThroughComments:Repair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.Any repairs to the structure ThroughComponent:Soffit/Facia/TrimDefect:In poor repairRequirement:Compliance, International Property Maintenance CodeIn poor repairComponent:Soffit/Facia/TrimDefect:In poor repairRequirement:Compliance, International Property Maintenance CodeLocation:Main Structure ThroughComments:Soffit/Facia/TrimDefect:In poor repairComments:Soffit/Facia/TrimDefect:Main Structure ThroughComments:Soffit/Facia/TrimDefect:Absence of paint			Defect:	Missing
Component: Exterior Walls Defect: In poor repair   Component: Exterior Walls Defect: In poor repair   Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Comments: Soffit/Facia/Trim Defect: In poor repair   Component: Soffit/Facia/Trim Defect: In poor repair   Comments: Soffit/Facia/Trim Defect: Main Structure Through   Comments: Soffit/Facia/Trim Defect: Main Structure Through   Comments: Soffit/Facia/Trim Defect: Absence of paint	1		Location:	Main Structure Throughout
Requirement: Compliance, International Property   Maintenance Code Location: Main Structure Through   Comments: Repair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.   Component: Soffit/Facia/Trim Defect: In poor repair   Component: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Comments: Soffit/Facia/Trim Defect: Absence of paint				v frames. Any
Maintenance Code Location: Main Structure Through   Repair/replace any broken, missing , damaged or rotted siding. Any repairs to the structure will require a building permit.   Component: Soffit/Facia/Trim Defect: In poor repair   Requirement: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Requirement: Soffit/Facia/Trim Defect: Main Structure Through   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure Through Main Structure Through   Comments: Soffit/Facia/Trim Defect: Absence of paint			Defect:	In poor repair
Component: Soffit/Facia/Trim Defect: In poor repair   Component: Compliance, International Property Main Structure Through   Maintenance Code Location: Main Structure Through   Comments: Repair/replace any otted, damaged or broken boards. Any repairs to the structure will require a building permit.   Component: Soffit/Facia/Trim Defect:   Defect: Main Structure Through   Comments: Soffit/Facia/Trim Defect:   Soffit/Facia/Trim Defect: Absence of paint			Location:	Main Structure Throughout
Requirement: Compliance, International Property Maintenance Code Location: Main Structure Through   Comments: Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Defect: Absence of paint			otted siding.	Any repairs to the
Comments: Maintenance Code Location: Main Structure Through   Repair/replace any rotted, damaged or broken boards. Any repairs to the structure will require a building permit. Main Structure Through   Component: Soffit/Facia/Trim Defect: Absence of paint			Defect:	In poor repair
Component: Soffit/Facia/Trim Defect: Absence of paint			Location:	Main Structure Throughout
			ds. Any repa	airs to the structure
Baguiramente Compliance International Property			Defect:	Absence of paint
		Compliance, International Property Maintenance Code	Location:	Main Structure Throughout
<b>Comments:</b> Scrape loose paint, repair where needed and paint to match.	omments:	Scrape loose paint, repair where needed and paint	to match.	

#### 818 Е 27ТН ST Areas that need attention:

# **Polk County Assessor**

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

			L	ocation	l			
Address	818 E 27TH	ST						
City	DES MC	DINES	Zip		50317	Jurisdiction	Des Moines	
District/Parcel 050/01232-000-000		00-000	Geoparcel	7824	-01-202-016	Status	Active	
			Nbhd/Pocket		DM16/Z	Tax Authority Group	DEM-C-DEM- 77131	
Submarket	Northeast Des	Moines	Appraiser	Bra	xton Peats 515- 286-3839			
		j	Map and Cu	rrent P	hotos - 1 Rec	ord		
Click	c on parcel to	get a no	ew listing					
901		830	901		Ph	oto Processed on 2	010-10-14 a	
825		828	825			i an	Margare .	
821		824	823					
819	8	918	11 817 817					
815		814	ST 813					
			809		. ji ,			
	<u>gger Map</u> Pol Google Map	k Count Pictom						
				storical	Photos			
			Owners	ship - 1	Record			
Ownership	Num		Na	ame		Recorded	Book/Page	
Title Holder	1	MUR	RUETA ESPIN	NOZA,	ANA M	2017-08-18	<u>16611/61</u>	
		Leg	gal Descriptio	on and I	Mailing Addı	ess		
LOT 20 BLK	2 FARWELL	PLACE	3		ANA M MURUETA ESPINOZA 814 E 27TH ST DES MOINES, IA 50317			
			Cur	rent Va	lues			
Туре	Class		K	ind	Land	Bldg	Total	

Туре	Class	Kind	Land	Bldg	Total				
2020 Value	Residential	Full	\$17,100	\$36,000	\$53,100				
Market Adjusted Cost Report									
Zoning - 1 Record									
Zoning Description SF Assessor Zoning									
N3C N3c Neighborhood District Residential									
City of Des M	oines Community Developm	ent Planning	and Urban Design	a 515 283-4182 (	2012-03-20)				

web.assess.co.polk.ia.us/cgi-bin/web/tt/infoqry.cgi?tt=card/card&dp=0500123200000&

Polk County Assessor 050/01232-000-000

			1801 000/01232-000-0		
		Land			
Square Feet	6,950	Acres	0.160	Frontage	50.0
Depth		Topography	Normal	Shape	Rectangle
Vacancy		Unbuildable	No		
		Residences - 1	Record		
		Residence	#1	-	-
Occupancy	Single Family	<b>Residence</b> Type	1 Story	Building Style	Bungalow
Year Built	1921	Number Families	1	Grade	5+05
Condition	Below Normal	Total Square Foot Living Area	828	Main Living Area	828
Basement Area	238	Enclosed Porch Area	32	Deck Area	120
Foundation	Brick	<b>Exterior Wall Type</b>	Hardboard	Roof Type	Gable
Roof Material	Asphalt Shingle	Heating	Gas Forced Air	Air Conditioning	100
Number Bathrooms	1	Bedrooms	2	Rooms	4
	12	8 	20 12 1s 7 34 7 12 12	34	
		10	Dack 10 120 10		

Sales - 3 Records

### Polk County Assessor 050/01232-000-000

Seller	Buyer	Sale Date Sale Price		Instrument	Book/Page
ELDON WOLTZ TRUST	MURUETA ESPINOZA, ANA M	<u>2017-08-18</u>	\$10,000	Deed	<u>16611/61</u>
ELDON WOLTZ, TRUST	WISEMAN, DIANE	<u>1997-02-28</u>	\$37,500	Contract	<u>7585/358</u>
CLOVER, JEFFREY D	ELDON WOLTZ TRUST	<u>1995-08-07</u>	\$15,000	Deed	<u>7242/83</u>

## **Recent Ownership Transfers**

Instrument Recording Instrument Realt/Dr											
Grantor Grantee			Date	CIIC	Date	0	Ty		Book/Pg		
WOLTZ PETER (Truste ELDOI WOLTZ	. C e)	C MURUETA ESPINOZA, ANA M		IOZA, 2017-08-18		2017 18	W		ustee arranty eed	<u>16611/61</u>	
Known WISEI DIANE	Formerly Known As WISEMAN, ELDON DIANE WOLTZ ————————————————————————————————————			1 2016 12 14 1		2017 10			rfeiture Contract	<u>16339/762</u>	
				Permits	- 1 R	ecord					
Year	Year Type Permit Sta			s Application			Reason R			leason1	
1989	Permit	Complete		1988-06-17			Demolish (		Jarage		
				Histor	ical Va	alues					
Yr	Туре		Clas	s	K	ind	La	nd	Bldg	Total	
2019	Assessm	nent Roll	Resi	dential		Full	\$17,1	00	\$36,000	\$53,100	
2017	Assessn	nent Roll	Resi	dential		Full	\$14,7	00	\$31,400	\$46,100	
2015	Assessn	nent Roll	Resi	dential		Full		00	\$29,200	\$42,900	
2013	Assessn	nent Roll	Resi	dential		Full	\$13,7	00	\$29,600		
2011	Assessm	nent Roll	Resi	sidential		Full	\$15,6	00	\$33,600	\$49,200	
2009	Assessm	nent Roll	Resi	Residential		Full	\$16,500		\$35,800	\$52,300	
2007	Assessm	Assessment Roll Res		esidential		Full	\$16,300		\$35,400		
2005	Assessm	ment Roll Resid		sidential		Full	\$15,0		\$34,000		
2003	Assessm	nent Roll		Residential		Full	\$12,8		\$29,630		
2001	Assessm	<u>nent Roll</u>		dential	_	Full	\$12,5		\$30,260		
1999	Assessm	nent Roll		dential	_	Full	\$7,6		\$24,850		
1997	Assessm	nent Roll		dential		Full	\$6,9		\$22,510		
1995	Assessm	nent Roll	Resi	dential	_	Full	\$6,0		\$19,600		
100-				4 .1 1	1	T 11	AF A	00	A17 200	000 700	

Full

Full

Full

Full

Residential

Residential

Residential

Residential

\$5,380

\$5,380

\$5,380

\$5,380

Assessment Roll

Assessment Roll

Assessment Roll

**Board Action** 

1993

1990

1990

1989

\$22,760

\$20,000

\$21,700

\$20,310

\$17,380

\$14,620

\$16,320

\$14,930

This template was last modified on Sun Jan 31 22:36:22 2021.





