Roll Call	Number
-----------	--------

Agenda Iter	n Number
_	39A

Date	August 9, 2021	

ABATEMENT OF PUBLIC NUISANCE AT 1305 McKINLEY AVE.

WHEREAS, the property located at 1305 McKinley Ave., Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Austin G. Brien, was notified more than thirty days ago to repair or demolish the main structure and as of this date has failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 17, Except the West 50 feet, in LAWN ARBOR ACRES, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa; AND The West ½ of Lot 16 in LAWN ARBOR ACRES, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 1305 McKinley Ave., has previously been declared a public nuisance;

The City Legal Department, through Special Counsel Ahlers & Cooney, P.C., is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by	to adopt
INIO YOU DY	ιο ασορι

FORM APPROVED:

Kristine Stone, Special Counsel

Ahlers & Cooney, P.C.

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT
COWNIE				
BOESEN				
GATTO				
GRAY	7			
MANDELBAUM				
voss				
WESTERGAARD				
TOTAL				
OTION CARRIED	***************************************		API	PROVED

Mayor

CERTIFICATE

I, P. Kay Cmelik, City Clerk of said City hereby certify that at a meeting of the City Council of said City of Des Moines, held on the above date, among other proceedings the above was adopted.

IN WITNESS WHEREOF, I have hereunto set my hand and affixed my seal the day and year first above written.

City	Clerk



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

39A

DATE OF NOTICE: March 10, 2021

DATE OF INSPECTION:

February 09, 2021

CASE NUMBER:

COD2021-00390

PROPERTY ADDRESS:

1305 MCKINLEY AVE

LEGAL DESCRIPTION:

W 1/2 LT 16 & -EX W 50F- LOT 17 LAWN ARBOR ACRES

AUSTIN G BRIEN Title Holder 1305 MCKINLEY AVE DES MOINES IA 50315

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Chad Sutherland

(515) 283-4181

Nid Inspector

DATE MAILED: 3/10/2021

MAILED BY: TSY

Areas that need attention: 1305 MCKINLEY AVE


Component: Requirement:	Interior Walls /Ceiling <u>Defect:</u> Fire damaged Complaince with Int Residential Code	
	<u>Location:</u> Main Structure Throughout	
Comments:	REPAIR/REPLACE ALL INTERIOR WALLS DAMAGED BY FIRE/SMOKE/WATER.	
Component:	Gas Lines <u>Defect:</u> Unknown	
<u>Requirement:</u>	Compliance with Int. Fuel Gas Code <u>Location:</u> Main Structure Throughout	
<u>Comments:</u>	ALL GAS LINES NEED TO BE TESTED BY LICENSED MECHANICAL CONTRACTOR. SHOW PROOF OF ACTIVITIY WITH RECEIPT.	
Component:	Mechanical System <u>Defect:</u> Unknown	
Requirement:	Licensed Contractor Certification <u>Location:</u> Main Structure Throughout	
Comments:	HAVE LICENSED MECHANICAL CONTRACTOR TEST SYSTEM TO DEEM IT IS SAFE. OBTAIN AND FINALIZE MECH. PERMIT FOR REPAIRS	
Component:	Plumbing System <u>Defect:</u> Leaks	
Requirement:	Plumbing Permit <u>Location:</u> Main Structure Throughout	
Comments:	REPLACE/REPLACE ALL DAMAGED AND LEAKING PIPES BU LICENSED PLUMBING CONTRACTOR. OBTAIN AND FINALIZE PLUMBING PERMIT.	
Component:	Roof <u>Defect:</u> Fire damaged	
Requirement:	Building Permit <u>Location:</u> Main Structure Throughout	
Comments:	REPAIR/REPLACE ANY DAMAGED DONE TO ROOF OR ROOF STRUCTURE BY LICENSED CONTRACTOR. OBTAIN AND FINALIZE BUILDING PERMIT.	
Component:	Electrical Lighting Fixtures <u>Defect:</u> Fire damaged	
Requirement:	Electrical Permit <u>Location:</u> Main Structure Throughout	
Comments:	REPAIR/REPLACE ALL FIXTURES DAMAGE BY WATER/FIRE/SMOKE.WORK MUST BE DONE BY LICENSED ELECTRICAL CONTRACTOR. OBTAIN AND FINALIZE ELECTRICAL PERMIT.	Ξ
Component:	Electrical Service <u>Defect:</u> Fire damaged	
Requirement:	Electrical Permit <u>Location:</u> Main Structure Throughout	
<u>Comments:</u>	REPAIR/REPLACE ALL ELECTRICAL COMPONENTS DAMAGED BY FIRE/SMOKE/WATER. WORK MUST BE DONE BY LICENSED ELECTRICAL CONTRATOR. OBTAIN AND FINALIZE ELECTRICAL PERMIT.	
Component: Requirement:	Electrical System Electrical Permit Location: Main Structure Throughout	
Comments:	REPAIR/REPLACE ALL ELECTRICAL COMPONENTS DAMAGED BY FIRE/SMOKE/WATER. WORK MUST BE DONE BY LICENSED ELECTRICAL CONTRATOR. OBTAIN AND FINALIZE ELECTRICAL PERMIT.	

Component:	Extense Books/During	Defect:	Fire damaged
Requirement:	Complaince with Int Residential Code		
		Location:	Main Structure Throughout
Comments:	A STATE OF THE STA	ID TAME	ALL DOODS NEED TO BE IN
<u>Commence</u>	REPAIR/REPLACE ALL EXTERIOR DOORS AN	ND JAMS.	ALL DOORS NEED TO BE IN
	GOOD WORKING ORDER.		
C	Floor Jaiota/Dooma	Defect:	Fire damaged
Component:	1 1001 2010(2) 2011110	Delecti	The damaged
Requirement:	Building Permit	Lacations	Main Structure Throughout
		LUCACIUII.	Main Structure Throughout
Comments:	REPAIR/REPLACE ANY FLOORING DAMAGE	D BY FIRE	S/SMOKE/WATER, IF
	FLOORING STRUCTURE IS COMPROMISED	REPAIRS	NEED TO BE DONE BY
	LICENSED CONTRACTOR, OBTAIN AND FIN	IALIZE BU	TLDING PERMIT.
	LICENSED CONTRACTOR, OBTAIN AND TEL		
Component:	Flooring	Defect:	Fire damaged
Requirement:	Complaince with Int Residential Code		
		Location:	Main Structure Throughout
Comments:			
	REPAIR/REPLACE ANY FLOORING DAMAGE	D RX LTK	E/SMOKE/WATEK, IF
	FLOORING STRUCTURE IS COMPROMISED	REPAIRS	NEED TO BE DONE BY
	LICENSED CONTRACTOR, OBTAIN AND FIN	VALIZE BU	JILDING PERMIT.
Component:	Furnace	Defect:	Unknown
And the second s		D 0.001.	Charletti
Requirement:	Compliance, Uniform Mechanics Code	Location	Main Structure Throughout
_		LUCALIUM	Figure Throughout
Comments:	FURNACE WILL NEED TO BE TESTED WITH	H LICENSE	ED MECHANICAL CONTRACTOR.
e	SHOW PROOF OF ACTIVITY WITH RECEIP		
V	· ·		
1			
Component:	See Comments	Defect:	See Comments
Component: Requirement:	See Comments Complaince with Int Residential Code		
			See Comments : Garage
	Complaince with Int Residential Code	Location	: Garage
Requirement:	Complaince with Int Residential Code The garage in its current condition does n	Location ot constitu	: Garage ute a public nuisance. However,
Requirement:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and	Location ot constitu	: Garage ute a public nuisance. However, y structure is immediately built
Requirement:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo	Location ot constitu no primar olished as	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory
Requirement: Comments:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo	Location ot constitution no primar olished as Code Sec	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory tion 134-343.
Requirement: Comments: Component:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo use only pursuant to Des Moines Municipal Smoke Detectors	Location ot constitu no primar olished as	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory
Requirement: Comments:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo	Location ot constitu no primar olished as Code Sec Defect:	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory tion 134-343. Missing
Requirement: Comments: Component:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo use only pursuant to Des Moines Municipal Smoke Detectors	Location ot constitu no primar olished as Code Sec Defect:	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory tion 134-343.
Requirement: Comments: Component:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo use only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code	Location ot constitution primar olished as Code Sec Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout
Component: Requirement: Requirement:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC	Location ot constitution primar olished as Code Sec Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout
Component: Requirement: Requirement:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demo use only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code	Location ot constitution primar olished as Code Sec Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout
Component: Requirement: Requirement:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC	Location ot constitution primar olished as Code Sec Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout
Component: Requirement: Requirement: Comments:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMORESIDENTIAL CODE,.	Location ot constitution primar olished as Code Sec Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout
Component: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,.	Location ot constitution primare no primare olished as Code Section Defect: Location OKE DETECTION	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ation 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH
Component: Requirement: Requirement: Comments:	Complaince with Int Residential Code The garage in its current condition does n if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMORESIDENTIAL CODE,.	Location ot constitu no primar olished as Code Sec Defect: Location OKE DETEC	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ation 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH
Component: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demolished on the property, the garage must be demolished only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit	Location ot constitution primare olished as Code Section Defect: Location Defect: Defect: Location	: Garage ute a public nuisance. However, y structure is immediately built well because it is an accessory ation 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged Main Structure Throughout
Component: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demolished on the property, the garage must be demolished only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGEI	Location ot constitution primare plished as Code Section Defect: Location Defect: Location Defect: Location Defect: Defect: Defect: Defect: Defect: Defect:	Garage Let a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged Main Structure Throughout KSMOKE/WATER. WORK MUST
Component: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demolished on the property, the garage must be demolished only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit	Location ot constitution primare plished as Code Section Defect: Location Defect: Location Defect: Location Defect: Defect: Defect: Defect: Defect: Defect:	Garage Let a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged Main Structure Throughout KSMOKE/WATER. WORK MUST
Component: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demolished on the property, the garage must be demolished only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGEI	Location ot constitution primare plished as Code Section Defect: Location Defect: Location Defect: Location Defect: Defect: Defect: Defect: Defect: Defect:	Garage Let a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged Main Structure Throughout KSMOKE/WATER. WORK MUST
Component: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does in if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGED BE DONE BY LICENSED CONTRACTOR.OB	Location ot constitu no primar olished as Code Sec Defect: Location OKE DETEC Defect: Location OFFICE OFFI OFFI OFFI OFFI OFFI OFFI OFFI OFF	E Garage Lite a public nuisance. However, y structure is immediately built well because it is an accessory Lition 134-343. Missing LI Main Structure Throughout LITORS IN COMPLIANCE WITH Fire damaged LE Main Structure Throughout /SMOKE/WATER. WORK MUST D FINALIZE BUILDING PERMIT
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGED BE DONE BY LICENSED CONTRACTOR.OB	Location ot constitution primare plished as Code Section Defect: Location Defect: Location Defect: Location Defect: Defect: Defect: Defect: Defect: Defect:	Garage Let a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged Main Structure Throughout KSMOKE/WATER. WORK MUST
Component: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does in if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGED BE DONE BY LICENSED CONTRACTOR.OB	Location ot constitu no primar olished as Code Sec Defect: Location OKE DETEC Defect: Location OBY FIRE, TAIN AND	E Garage Lite a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing LE Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged LE Main Structure Throughout /SMOKE/WATER. WORK MUST OFINALIZE BUILDING PERMIT
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGED BE DONE BY LICENSED CONTRACTOR.OB	Location ot constitu no primar olished as Code Sec Defect: Location OKE DETEC Defect: Location OBY FIRE, TAIN AND	E Garage Lite a public nuisance. However, y structure is immediately built well because it is an accessory Lition 134-343. Missing LI Main Structure Throughout LITORS IN COMPLIANCE WITH Fire damaged LE Main Structure Throughout /SMOKE/WATER. WORK MUST D FINALIZE BUILDING PERMIT
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Comments: Comments:	Complaince with Int Residential Code The garage in its current condition does not the primary structure is demolished and on the property, the garage must be demolished on the property of t	Location ot constitution primariolished as Code Secondarion oke Defect: Location	E Garage Lite a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing LE Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged LE Main Structure Throughout /SMOKE/WATER. WORK MUST OFINALIZE BUILDING PERMIT
Component: Requirement: Comments: Comments: Comments: Comments: Comments: Requirement: Requirement: Requirement:	Complaince with Int Residential Code The garage in its current condition does not if the primary structure is demolished and on the property, the garage must be demouse only pursuant to Des Moines Municipal Smoke Detectors Complaince with Int Residential Code STRUCTURE WILL NEED OPERATING SMC RESIDENTIAL CODE,. Trusses Building Permit REPAIR/REPLACE ALL TRUSSES DAMAGED BE DONE BY LICENSED CONTRACTOR.OB	Location ot constitution primariolished as Code Secondarion oke Defect: Location	E Garage Lite a public nuisance. However, y structure is immediately built well because it is an accessory ction 134-343. Missing LE Main Structure Throughout CTORS IN COMPLIANCE WITH Fire damaged LE Main Structure Throughout /SMOKE/WATER. WORK MUST OFINALIZE BUILDING PERMIT


Defects Con Comments						
<u>Component:</u> Utilities <u>Defect:</u> See Comments						
Requirement: Complaince with Int Residential Code						
<u>Location:</u> Main Structure Througho	v it					
	,uc					
Comments: ALL UTILITIES NEED TO BE CONNECTED TO STRUCTURE AND IN WORKING						
ORDER.						
Component: Windows/Window Frames Defect: Cracked/Broken						
Requirement: Complaince with Int Residential Code						
<u>Location:</u> Main Structure Througho	Jut					
Comments: DEDAYD (DEDI ACE ALL MENDOWIC AND EDAMES THAT ADE DAMACED						
REPAIR/REPLACE ALL WINDOWS AND FRAMES THAT ARE DAMAGED.						
Component: Wiring Defect: Fire damaged						
Requirement: Electrical Permit						
Location: Main Structure Throughout	out					
Comments:						
REPAIR/REPLACE ALL ELECTRICAL COMPONENTS DAMAGED BY						
FIRE/SMOKE/WATER, WORK MUST BE DONE BY LICENSED ELECTRICAL	FIRE/SMOKE/WATER. WORK MUST BE DONE BY LICENSED ELECTRICAL					
	CONTRATOR, OBTAIN AND FINALIZE ELECTRICAL PERMIT.					


39A

							Assigned	Done	Updated	
	Description	Date 1	Date 2	Date 3	Hold	Disp	To	Ву	Ву	Notes
COD202	1-00390	1305 MCKINLE	EYAVE							
	Complaint Received			2/10/21	None			CRS1	CRS1	
	PN Structure Inspection	2/9/21	2/9/21	2/9/21	None	FAIL	CRS1	CRS1	CRS1	3-3-2021 MAIN STRUCTURE HAS MAJOR FIRE AND SMOKE DAMAGED. MULTIPLE WINDOWS MISSING. FLOORING AND WALLS HAVE HOLES AND MAJOR DEFECTS. ELECTRICAL SYSTEM IS COMPROMISSED. PLUMBING SUPPLY LINE LEAKING. 1ST INSPECTION WAS ON 2/9/2021 FOR EXTERIOR AND WAITED FOR OWNER TO LET US IN FOR 2ND INSPECTON FOR INTERIOR. CRS1
	PN Supervisor Review	3/3/21	3/4/21	3/5/21	None	DONE	CEH	CEH	CEH	PN house fire.
	PN Monitor	3/3/21	4/7/21	4/9/21	None	DONE	CRS1	CRS1	CRS1	4-09-2021 walked property no changes seen. also have a junk and debris case open on property. crs1
	PN Inspection Fee	3/3/21	3/8/21	3/8/21	None	DONE	TSY	TSY	TSY	3-3-2021 PLEASE BILL OUT FOR INSPECTION FEE AND PICTURES.
	PN Posted			3/3/21	None		CRS1	CRS1	CRS1	
	NID PN Notice			3/10/21	None	DONE	CRS1	TSY	TSY	
	PN Monitor	4/9/21	6/14/21		None		CRS1		CRS1	
	NID PN Notice			4/16/21	None	DONE	CRS1	TSY	TSY	added the mortgage company's. tsy
	Send to Publish	4/27/21	4/28/21	4/29/21	None	DONE	TSY	TSY	TSY	sent to DSM for publication of the notices. Due to unable to get owner servied the paper work. tsy
	Publication Recheck	5/1/21	5/8/21	4/29/21	None	DONE		TSY	TSY	publication of notice on May 1st, 2021. tsy












Polk County Assessor

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

Location						
Address 1305 MCKINLEY AVE						
City	DES MOINES	Zip	50315	Jurisdiction	Des Moines	
District/Parcel	120/02895-004-000	Geoparcel	7824-21-353-046	Status	<u>Active</u>	
School	Des Moines	Nbhd/Pocket	DM35/Z	Tax Authority Group	DEM-C-DEM- 77131	
Submarket	South Des Moines	Appraiser	Andrew Rand 515- 286-3368			

Map and Current Photos - 1 Record





Historical Photos

Ownership - 1 Record				
Ownership	Num	Name	Recorded	Book/Page
Title Holder	1	BRIEN, AUSTIN G	2011-03-14	13796/213

Legal Description and Mailing Address

W 1/2 LT 16 & -EX W 50F- LOT 17 LAWN ARBOR ACRES

AUSTIN G BRIEN 1305 MCKINLEY AVE DES MOINES, IA 50315-3832

Current Values

Туре	Class	Kind	Land	Bldg	Total
2021 Value	Residential	Full	\$31,900	\$130,500	\$162,400


Assessment Roll Notice Market Adjusted Cost Report

Auditor Adjustments to Value

Category	Name	Information
2020 Homestead Credit	BRIEN, AUSTIN G	Application #260304

Zoning - 1 Record

Zoning		Description	SF	Assessor Zoning		
N5	N5 Neighbo	rhood District		Residential		
City of Des Moi	nes Communit	y Development Planning	and Urban Des	Urban Design 515 283-4182 (2012-03-20)		
		Land				
Square Feet	Square Feet 20,621		0.473	Frontage	119.2	
Depth		Topography	Normal	Shape	Rectangle	
Vacancy	No	Unbuildable	No			
		Residences - 1	Record			
		Residence	#1			
Occupancy	Single Family	Residence Type	1.5 Stories	Building Style	Early 20s	
Year Built	1924	Number Families	1	Grade	3-10	
Condition	Normal	Total Square Foot Living Area	1816	Main Living Area	1097	
Upper Living Area	719	Basement Area	1073	Enclosed Porch Area	168	
Patio Area	400	Foundation	Masonry	Exterior Wall Type	Brick	
Brick%	100	Roof Type	Gable	Roof Material	Asphal Shingle	
Number Fireplaces	1	Heating	Gas Forced Air	Air Conditioning	100	
Number Bathrooms	2	Number Toilet Rooms	1	Bedrooms	4	
Rooms	8					



Detached Structures - 1 Record

Detached Structure #101						
Occupancy	Garage	Construction Type	Type Frame Measurement Code Dimens		Dimensions	
Measure 1	14	Measure 2	22	Story Height	1	
Grade	4	Year Built	1963	Condition	Normal	

Historical Values

Yr	Туре	Class	Kind	Land	Bldg	Total
2021	Assessment Roll	Residential	Full	\$31,900	\$130,500	\$162,400
2019	Assessment Roll	Residential	Full	\$29,900	\$120,900	\$150,800
2017	Assessment Roll	Residential	Full	\$26,100	\$108,600	\$134,700
2015	Assessment Roll	Residential	Full	\$24,200	\$101,300	\$125,500
2013	Assessment Roll	Residential	Full	\$23,200	\$98,300	\$121,500
2012	Assessment Roll	Residential	Full	\$23,200	\$105,100	\$128,300

This template was last modified on Thu Jun 3 19:39:49 2021 .