

Date August 23, 2021

ABATEMENT OF PUBLIC NUISANCE AT 2009 SW 9th STREET

WHEREAS, the property located at 2009 SW 9th Street, Des Moines, Iowa, was inspected by representatives of the City of Des Moines who determined that the main structure in its present condition constitutes not only a menace to health and safety but is also a public nuisance; and

WHEREAS, the Titleholder, Judith A Phillips, and Mortgage Holder, Bank of the West, were notified more than thirty days ago to repair or demolish the main structure and as of this date have failed to abate the nuisance.

NOW THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DES MOINES, IOWA:

The main structure on the real estate legally described as Lot 151 in FIRST PLAT OF CLIFTON HEIGHTS, an Official Plat, now included in and forming a part of the City of Des Moines, Polk County, Iowa, and locally known as 2009 SW 9th Street, has previously been declared a public nuisance;

The City Legal Department is hereby authorized to file an action in district court to obtain a decree ordering the abatement of the public nuisance, and should the owner(s) fail to abate the nuisance, as ordered, that the matter may be referred to the Department of Engineering which will take all necessary action to demolish and remove said structure.

Moved by_____to adopt.

FORM APPROVED:

/s/Megan Norberg

Megan Norberg, Assistant City Attorney

COUNCIL ACTION	YEAS	NAYS	PASS	ABSENT	CERTIFICATE
COWNIE					
BOESEN					I, P. Kay Cmelik, City Clerk of said City hereby
GATTO					certify that at a meeting of the City Council of said
GRAY					City of Des Moines, held on the above date, among other proceedings the above was adopted.
MANDELBAUM					other proceedings the above was adopted.
VOSS					IN WITNESS WHEREOF, I have hereunto set my
WESTERGAARD					hand and affixed my seal the day and year first
TOTAL					above written.
MOTION CARRIED			API	PROVED	
				Mavor	City Clerk

Polk County Assessor

Polk County Assessor 010/00679-000-000

111 Court Avenue #195 Des Moines, IA 50309-0904 (515) 286-3014 Fax (515) 286-3386 polkweb@assess.co.polk.ia.us

		Lo	ocation			
Address	2009 SW 9TH ST					
City	DES MOINES	Zip	5	0315	Jurisdiction	Des Moines
District/Parcel	010/00679-000-000	Geoparcel	7824-16-203	3-002	Status	Active
School	Des Moines	Nbhd/Pocket	t DM26/Z		Tax Authority Group	
Submarket	South Des Moine	Appraiser	Joseph Petersc 28	n 515- 5-3011		
		Map and Cur	rent Photos - 1	l Recor	d	
Clic	k on parcel to get a	new listing				
		\	-	Phot	o Processed on	2017-04-18 a
	HILLSID	E AVE	- 🖗	É.	ANT	A AN
ST	2005	2002	- 2	A	刘徽建	A B
HT9 V	2009					
MS	2013	2008			- 17	
	2019	2012	je.			
	2025	2018		- II.	And a state	South Party
	<u>gger Map</u> <u>Polk Cou</u> <u>Google Map</u> <u>Picto</u>	<u>nty GIS</u> metry				
L		Hist	orical Photos			
		Ownersh	nip - 1 Record			
Ownership	Num	Nan			Recorded	Book/Page
Title Holder	1	PHILLIPS, JUD			1992-02-12	<u>6503/429</u>
	L	egal Description	and Mailing	Addres	S	
LOT 151 1ST PLAT OF CLIFTON HGTS DES MOINES, IA 50315-1197						
		Curr	ent Values			
Type	Class	Ki	nd	Land	Bldg	Total

Туре	Class	Kind	Land	Bldg	Total	
2021 Value	Residential	Full	\$13,200	\$76,400	\$89,600	
A DUDLY MALE Adjusted Cost Depart						

Assessment Roll Notice Market Adjusted Cost Report


Auditor Adjustments to Value

Category	Name	Information
2020 Homestead Credit	PHILLIPS, JUDITH A	Application <u>#20134</u>

Polk County Assessor 010/00679-000-000

Zoning		Description		SF	Assess	or Zoning
N5	N5 Neighbor	N5 Neighborhood District			Res	idential
City of Des Moines Community Development Planning and Urban Design 515 283-4182 (2012-03-20)						
		Land				
Square Fee	t 6,520	Acres		0.150	Frontage	50.0
Depth	n 126.0	Topography	N	ormal	Shape	Rectangle
Vacancy	y No	Unbuildable		No		
		Residences -	1 Reco	ord		
		Residenc	e #1			
Occupancy	Single Family	Residence Type	St	1.5 ories	Building Style	Conventional
Year Built	1935	Number Families		1	Grade	4+00
Condition	Below Normal	Total Square Foot Living Area		1423	Main Living Area	876
Upper Living Area	547	Basement Area		816	Open Porch Area	348
Foundation	Brick	Exterior Wall Type	-	/letal iding	Roof Type	Gable
Roof Material	Asphalt Shingle	Heating	Fo	Gas orced Air	Air Conditioning	100
Number Bathrooms	2	Bedrooms		3	Rooms	8





Historical Values

Yr	Туре	Class	Kind	Land	Bldg	Total
2021	Assessment Roll	Residential	Full	\$13,200	\$76,400	\$89,600
2019	Assessment Roll	Residential	Full	\$11,500	\$66,100	\$77,600
2017	Assessment Roll	Residential	Full	\$10,400	\$61,700	\$72,100
2015	Board Action	Residential	Full	\$9,400	\$57,900	\$67,300
2015	Assessment Roll	Residential	Full	\$9,900	\$82,000	\$91,900
2013	Assessment Roll	Residential	Full	\$9,800	\$83,400	\$93,200
2011	Assessment Roll	Residential	Full	\$9,700	\$82,600	\$92,300
2009	Assessment Roll	Residential	Full	\$10,400	\$87,400	\$97,800
2007	Assessment Roll	Residential	Full	\$10,000	\$75,000	\$85,000
2005	Assessment Roll	Residential	Full	\$10,000	\$70,300	\$80,300
2003	Assessment Roll	Residential	Full	\$8,960	\$63,760	\$72,720
2001	Assessment Roll	Residential	Full	\$7,640	\$61,240	\$68,880
1999	Assessment Roll	Residential	Full	\$10,400	\$51,590	\$61,990
1997	Assessment Roll	Residential	Full	\$9,260	\$45,940	\$55,200

web.assess.co.polk.ia.us/cgi-bin/web/tt/infoqry.cgi?tt=card/card&dp=01000679000000&

Polk County Assessor 010/00679-000-000

	Yr	Туре	Class	Kind	Land	Bldg	Total
1	1995	Assessment Roll	Residential	Full	\$8,420	\$41,760	\$50,180
	1993	Assessment Roll	Residential	Full	\$7,870	\$39,030	\$46,900
	1991	Assessment Roll	Residential	Full	\$7,150	\$35,480	\$42,630
L	1991	Was Prior Year	Residential	Full	\$7,150	\$29,750	\$36,900

This template was last modified on Thu Jun 3 19:39:49 2021 .



PUBLIC NUISANCE NOTICE OF INSPECTION NEIGHBORHOOD INSPECTION DIVISION COMMUNITY DEVELOPMENT DEPARTMENT CITY OF DES MOINES, IOWA

DATE OF NOTICE: May 1	3, 2021	DATE OF INS	SPECTION:	February 08, 2021
CASE NUMBER:	COD2021-00389		3	
PROPERTY ADDRESS:	2009 SW 9TH ST			
LEGAL DESCRIPTION:	LOT 151 1ST PLAT OF CLI	FTON HGTS	9 9	

JUDITH A PHILLIPS Title Holder 2201 E PARK AVE APT 106 DES MOINES IA 50320

BANK OF THE WEST Mortgage Holder - NANDITA BAKHSHI, PRESIDENT 801 GRAND AVE # 300 DES MOINES IA 50309

An inspection of the referenced property was conducted for its conformance to the Municipal Code of the City of Des Moines. It has been determined from that inspection that the dwelling currently constitutes not only a menace to health and safety, but is also a public nuisance. Accordingly, the dwelling will be placarded as unfit for human habitation pursuant to the Municipal Code of the City of Des Moines and the Code of Iowa.

If not occupied at the present time, the dwelling is to remain vacant and unoccupied until occupancy is authorized by this office. If the dwelling is occupied, it must be vacated immediately. If procedures to vacate the premises are not undertaken immediately upon receipt of this notice, and in no case later than seven (7) days, the City will issue a Municipal Infraction in accordance with Section 60-192 and 60-191 pursuant to the Municipal code of the City of Des Moines. Additionally, if the property had a Certificate of Inspection, it is hereby revoked.

Attached is a listing of the violations existing on the date of the inspection and a recommendation as to the remedial action required to correct such violations. The violations noted must be corrected within 30 days from date of notice. Failure to correct these violations will result in a request to the City Council to approve legal action. As a result of this public nuisance action there will be costs incurred by the City. Costs will be billed out when the nuisance has been abated. Failure to pay the costs will result in collection by assessment to the property or personal judgment.

ALL ELECTRICAL, MECHANICAL, PLUMBING, AND STRUCTURAL COMPONETS IN NEED OF REPLACEMENT OR REPAIR, ARE TO BE BROUGHT TO MINIMUM CODE REQUIREMENTS WITH NECESSARY PERMITS AS REQUIRED TO MEET CITY CODES.

Appropriate building permits may be required for those violations noted in the "Special Requirements" section on the notice. Should you have questions regarding permits, contact the Permit and Development Center at (515) 283-4200. All work performed by a contractor or you must be completed in a workmanlike manner. If you plan to renovate the structure and it has been vacant for a period in excess of one year, there may be zoning issues, which will affect the proposed use of the structure and/or real estate. Please contact the Development Zoning Division at (515) 283-4207 to determine what the legal use for the structure and/or the real estate is prior to commencement of any renovation.

If you believe the building is beyond repair and decide to remove it, all debris must be removed from the property and the basement excavation if any, filled in the manner required by the City. You are encouraged to arrange for this demolition yourself; however a demolition permit must be obtained from the Building Department. In the event you are unable to arrange for demolition, you may sign a waiver voluntarily authorizing the City to do so. However, the City may take a personal judgment against you for the costs of removal.

If you no longer own the property, notify us in writing of the name, address, and telephone number of the new owner. A copy of the real estate contract or deed, if it has not been recorded at the County Recorder's Office, shall likewise be furnished to the Neighborhood Inspection Division.

Should you have any questions, feel free to call. I can usually be reached between 8:00am and 9:00am, Monday through Friday.

Chad Sutherland

(515) 283-4181

Nid Inspector

DATE MAILED: 5/13/2021

MAILED BY: TSY

32A

Areas that need attention: 2009 SW 9TH ST

.

.

Component:	Window Glazing/Paint	Defect:	Cracked/Broken
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Main Structure Throughout
Comments:	REPAIR/REPLACE ALL BROKEN/CRACKED		
		OLALING.	
Component:	Windows/Window Frames	Defect:	Missing
<u>Requirement:</u>	Compliance, International Property Maintenance Code	Location:	Main Structure Throughout
Comments:	REPAIR/REPLACE ALL WINDOWS AND FR		
	REPLACE ALL ROTTEN WOOD AROUND F		
		1	
Component:	Wiring	Defect:	Fire damaged
<u>Requirement:</u>	Electrical Permit	Location:	Main Structure Throughout
Comments:	REPAIR/REPLACE ALL ELECTRICAL COMP		
	SMOKE/FIRE/WATER. WORK MUST BE DO		
	CONTRACTOR. OBTAIN AND FINALIZE PE	RMIT	
Component:	Electrical Lighting Fixtures	Defect:	Fire damaged
<u>Requirement:</u>	Electrical Permit	Location:	Main Structure Throughout
Comments:	REPAIR/REPLACE ALL ELECTRICAL COMP		
	SMOKE/FIRE/WATER. WORK MUST BE DO	ONE BY LICE	
	CONTRACTOR. OBTAIN AND FINALIZE PE	RMIT	
Component:	Interior Walls /Ceiling	Defect:	Flame/Smoke Spread
<u>Component:</u> <u>Requirement:</u>	Interior Walls /Ceiling Unknown		Hame/Smoke Spread Main Structure Throughout
	Unknown	Location:	Main Structure Throughout
Requirement:		Location:	Main Structure Throughout
Requirement:	Unknown	<u>Location:</u> DAMAGED F	Main Structure Throughout ROM SMOKE/FIRE/WATER.
Requirement: Comments: Component:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System	Location:	Main Structure Throughout
<u>Requirement:</u> <u>Comments:</u>	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I	Location: DAMAGED F Defect:	Main Structure Throughout ROM SMOKE/FIRE/WATER.
Requirement: Comments: Component:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System	Location: DAMAGED F Defect: Location:	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout
Requirement: Comments: Component: Requirement:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code	Location: DAMAGED F Defect: Location: BING CONTI	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE	Location: DAMAGED F Defect: Location: BING CONTI R.	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE
Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE	Location: DAMAGED F Defect: Location: BING CONTI	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility
Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE	Location: DAMAGED F Defect: Location: BING CONTI R. Defect:	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE
Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location:	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Comments: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location:	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code ALL UTILITIES WILL NEED TO BE CONNE	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location: CTED AND	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout WORKING TO STRUCTURE.
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Requirement: Component: Requirement: Component: Component:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code ALL UTILITIES WILL NEED TO BE CONNE Smoke Detectors	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location:	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code ALL UTILITIES WILL NEED TO BE CONNE	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location: CTED AND	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout WORKING TO STRUCTURE.
Requirement: Comments: Component: Requirement: Comments: Component: Requirement: Component: Requirement: Component: Requirement: Component: Requirement: Component: Component:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code ALL UTILITIES WILL NEED TO BE CONNE Smoke Detectors Compliance, International Property Maintenance Code STRUCTURE WILL NEED FUNCTIONING S	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location: CTED AND Defect: Location: MOKE DET	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout WORKING TO STRUCTURE. Missing Main Structure Throughout
Requirement: Comments: Component: Requirement: Comments: Comments: Component: Requirement: Comments: Component: Requirement: Comments:	Unknown REPAIR/REPLACE ALL INTERIOR WALLS I Plumbing System Compliance with Uniform Plumbing Code NEED A RECIEPT FROM LICENCED PLUMI SYSTEM TO BE IN SAFE WORKING ORDE Utilities Compliance, International Property Maintenance Code ALL UTILITIES WILL NEED TO BE CONNE Smoke Detectors Compliance, International Property Maintenance Code	Location: DAMAGED F Defect: Location: BING CONTI R. Defect: Location: CTED AND Defect: Location: MOKE DET	Main Structure Throughout ROM SMOKE/FIRE/WATER. Unknown Main Structure Throughout RACTOR DEEMING THE Disconnected Utility Water/Gas/Electric Main Structure Throughout WORKING TO STRUCTURE. Missing Main Structure Throughout

<u>Component:</u> <u>Requirement:</u>	Compliance with Int. Exiting Building	<u>Defect:</u> ocation:	See Comments Main Structure Throughout
<u>Comments:</u>	REPAIR/REPLACE ANY ROOF DAMAGED.	4 27	
<u>Component:</u> <u>Requirement:</u>	Electrical System D Electrical Permit	efect:	Fire damaged
Commontes	Lo	ocation:	Main Structure Throughout
<u>Comments:</u>	REPAIR/REPLACE ALL ELECTRICAL COMPONI SMOKE/FIRE/WATER. WORK MUST BE DONE CONTRACTOR. OBTAIN AND FINALIZE PERM	BY LICE	
<u>Component:</u> <u>Requirement:</u>	Mechanical System <u>D</u> Compliance, Uniform Mechanics Code	efect:	Unknown
		ocation:	Main Structure Throughout
<u>Comments:</u>	NEED A RECIEPT FROM LICENCED MECHANI SYSTEM TO BE IN SAFE WORKING ORDER.	CAL CON	TRACTOR DEEMING THE
Component:		efect:	Flame/Smoke Spread
<u>Requirement:</u>	Building Permit	ocation:	Main Structure Throughout
<u>Comments:</u>	REPAIR/REPLACE ALL STRUCTURAL COMPON AND FINALIZE BUILDING PERMIT.		

ĩ.

